



NRA

National Rivers Authority

South West Region

**ENVIRONMENTAL PROTECTION
INTERNAL DRAFT
WATER QUALITY TECHNICAL NOTE**

**IDENTIFICATION OF POLLUTION
INCIDENTS POTENTIALLY
AFFECTING ROUTINE MONITORING
SITES. 1991 - 1992**

May 1993

Author: J Lightband
Technical Assistant

**C V M Davies
Environmental Protection
Manager**

IDENTIFICATION OF POLLUTION INCIDENTS POTENTIALLY AFFECTING ROUTINE
MONITORING SITES 1991 - 1992

INTRODUCTION

This report contains information on pollution incidents possibly affecting watercourses in the South West during 1991 and 1992. The nearest downstream routine river monitoring sites, chemical and biological, are given in order to show to what extent the sites may, or may not, be affected by the pollution incidents.

The information was taken from PILS (Pollution Incident Logging System) reports and the NRA Monthly Pollution reports.

ENVIRONMENT AGENCY



047349

KEY TO CATEGORIES OF DATA

SITE: Site reference number for the nearest downstream biological monitoring site.

URN: User Reference Number for the nearest downstream chemical monitoring site.

RIVER: Receiving water of pollution. Parentheses show that the monitoring site is not in the receiving water but the next watercourse given.

NAME: Probable source of pollution.

PILS NUMBER: PILS reference number for incident.

POLLNGR: The National Grid Reference number of the location of pollution.

CATEGORY: Categories, 1 and 2, used by Pollution to show grade of significance, 1 being the most significant.

LENGTHAFF: Estimated length of the part of the watercourse possibly affected by pollution.

SAMPLE: Y = sample was taken
N = no sample was taken

LIKELIHOOD: This is an estimate of the likelihood of the associated downstream site being affected by pollution.
A = probable; B = possible; U = unlikely

INCIDENT DESCRIPTION: This is divided into four parts, based on the PILS pollution incident code:
ORIGIN (where?)
CAUSE (How?)
REASON (Why?)
NATURE (What?)

IDENTIFICATION OF POLLUTION INCIDENTS POTENTIALLY AFFECTING
ROUTINE MONITORING SITES 1991 - 1992

Page No. 1
18/06/93

Catch 02B SITE NR06.0202 URN R02B001 RECNO 66
DATE 30/01/92
RIVER (HAMPTON STREAM) AXE
NAME WOODEND FARM, SHUTE, AXMINSTER
PILS Number POLLNGR SY25209640 CATEGORY 1
LENGTHAFF 1.50 Sample Y Likelihood? A
Incident Description
ORIGIN 3V -- Spraying to land (Land runoff)
CAUSE 9 -- Runoff
REASON D -- Mechanical/electrical plant failure
NATURE 2K -- Animal waste/slurry
Comments: SEVERE DISCOLOURATION.

Catch 02B SITE NR06.0210 URN R02B005 RECNO 34
DATE 24/07/91
RIVER COLY
NAME BONEWAYNE FARM, COLYTON
PILS Number POLLNGR SX21609480 CATEGORY 2
LENGTHAFF 3.00 Sample Y Likelihood? A
Incident Description
ORIGIN 3P -- Silage stores
CAUSE 1 -- Leakage
REASON C -- Inadequate design/capacity
NATURE 2M -- Silage liquor
Comments:

Catch 02B SITE NR06.0204 URN R02B008 RECNO 73
DATE 01/03/92
RIVER (TRIB) UMBORNE BROOK
NAME DEEPCUL FARM, SHUTE
PILS Number POLLNGR SY23809840 CATEGORY 1
LENGTHAFF 1.00 Sample Y Likelihood? U
Incident Description
ORIGIN 3A -- Cattle slurry store
CAUSE 3 -- Overflow
REASON X -- Unknown
NATURE 2K -- Animal waste/slurry
Comments: SITES 5 KM D/S. FISH KILL IN TRIB ONLY.

Catch 02B SITE NR06.0207 URN R02B010 RECNO 77
DATE 18/03/92
RIVER OFFWELL BROOK
NAME COOKSHAYES FARM, NORTHLEIGH
PILS Number POLLNGR SY21409670 CATEGORY 2
LENGTHAFF 0.00 Sample Y Likelihood? B
Incident Description
ORIGIN 3W -- Farm drainage
CAUSE 6 -- Effluent discharge
REASON C -- Inadequate design/capacity
NATURE 2K -- Animal waste/slurry
Comments: SITES 1.5 KM D/S. LENGTH AFFECTED NOT SPECIFIED.

Catch 02C SITE NR06.0212 URN R02C002 RECNO 13
DATE 29/03/91
RIVER (LAND DRAIN) AXE
NAME SEABOROUGH MANOR FARM
PILS Number POLLNGR ST44000550 CATEGORY 1
LENGTHAFF 10.00 Sample Y Likelihood? A
Incident Description
ORIGIN 3K -- Pig slurry treatment plant
CAUSE 4 -- Burst
REASON D -- Mechanical/electrical plant failure
NATURE 2K -- Animal waste/slurry
Comments: FISH KILL - 250 TROUT. OTHER SITES AFFECTED: R02C003/0213.

Catch 02C SITE NR06.0234 URN R02C007 RECNO 35
DATE 30/07/91
RIVER (WEYCROFT STREAM) AXE
NAME MILLWEY RISE IND. EST. AXMINSTER
PILS Number POLLNGR SY30659980 CATEGORY 2
LENGTHAFF 2.00 Sample Y Likelihood? A
Incident Description
ORIGIN 2E -- Acid Processing
CAUSE 6 -- Effluent discharge
REASON 5 -- Poor operational practise
NATURE 2J -- Industrial effluent
Comments: CLAYS AND METALS FROM CERAMICS FACTORY

IDENTIFICATION OF POLLUTION INCIDENTS POTENTIALLY AFFECTING
ROUTINE MONITORING SITES 1991 - 1992

Page No. 2
18/06/93

Catch 02C SITE NR06.0220 URN R02C010 RECNO 74
DATE 11/03/92
RIVER FORTON BROOK
NAME BARTLETT CONSTRUCTION, CHARD
PILS Number 62007148 POLLNGR ST32950840 CATEGORY 2
LENGTHAFF 4.00 Sample Y Likelihood? A
Incident Description
ORIGIN 2F -- Building site
CAUSE 1 -- Leakage
REASON X -- Unknown
NATURE 3A -- Diesel
Comments: 500 LTRS LIGHT OIL.

Catch 02C SITE NR06.0219 URN R02C015 RECNO 48
DATE 14/10/91
RIVER (HOLLOWELL BROOK) WHATLEY STREAM
NAME PUTHILL FARM, CRICKET ST THOM. EST.
PILS Number 62002984 POLLNGR ST37500780 CATEGORY 2
LENGTHAFF 3.00 Sample N Likelihood? A
Incident Description
ORIGIN 3A -- Cattle slurry store
CAUSE 1 -- Leakage
REASON D -- Mechanical/electrical plant failure
NATURE 2K -- Animal waste/slurry
Comments: SITES 2 KM D/S.

Catch 02C SITE NR06.0216 URN R02C017 RECNO 20
DATE 04/06/91
RIVER (HEWISH STREAM) CLAPTON STREAM
NAME COOMBE FARM, CREWKERNE
PILS Number 62002569 POLLNGR ST41000960 CATEGORY 2
LENGTHAFF 4.00 Sample N Likelihood? A
Incident Description
ORIGIN 3W -- Farm drainage
CAUSE C -- Washing
REASON 5 -- Poor operational practise
NATURE 22 -- Other trade effluent
Comments: FISH KILL - OVER 50 REPORTED. SILT AND DEBRIS FROM CLEANING OF FARM POND.

Catch 02C SITE NR06.0242 URN R02C018 RECNO 91
DATE 18/05/92
RIVER (TRIB) TEMPLE BROOK
NAME BURSTOCK MANOR FARM, BURSTOCK
PILS Number 31001678 POLLNGR ST42100310 CATEGORY 2
LENGTHAFF 3.00 Sample Y Likelihood? B
Incident Description
ORIGIN 32 -- Farm premises/land other
CAUSE 2 -- Spillage
REASON 2 -- Other reasons for incident
NATURE 3A -- Diesel
Comments: 200-300 GALS RED DIESEL

Catch 02D SITE NR06.0228 URN R02D001 RECNO 167
DATE 02/11/92
RIVER CARRY BROOK VIA DITCH
NAME MILLHAYES COTTAGE, STOCKLAND
PILS Number 62006313 POLLNGR ST23400370 CATEGORY 1
LENGTHAFF 0.00 Sample N Likelihood? B
Incident Description
ORIGIN 1A -- Public highway - Land other (not farm)
CAUSE 1 -- Leakage
REASON X -- Unknown
NATURE 3B -- Heating oil
Comments: SITES ABOUT 1.5 KM D/S. ABOUT 300 GALLONS HEATING OIL, LEAK BEGINNING 1.11.93.

Catch 04A SITE NR06. URN RECNO 171
DATE 22/12/92
RIVER BUDLEIGH BROOK
NAME UNKNOWN
PILS Number 62007643 POLLNGR SY07208440 CATEGORY 1
LENGTHAFF 1.50 Sample N Likelihood?
Incident Description
ORIGIN 5B -- Sewer storm overflow Plc
CAUSE 8 -- Direct discharge
REASON X -- Unknown
NATURE 1X -- Other Chemical
Comments: NO SITES DOWNSTREAM. FISH KILL: 15 BROWN TROUT. CHLORINE BASED BLEACH.

IDENTIFICATION OF POLLUTION INCIDENTS POTENTIALLY AFFECTING
ROUTINE MONITORING SITES 1991 - 1992

Page No. 3
18/06/93

Catch 048 SITE NR06. URN RECNO 172
DATE 30/12/92
RIVER LITTLEHAM BROOK
NAME MAER FARM, EXMOUTH
PILS Number 62008827 POLLNGR SY02008060 CATEGORY 1
LENGTHAFF 1.00 Sample Y Likelihood?
Incident Description
ORIGIN 3Q -- Arable land
CAUSE 9 -- Runoff
REASON 5 -- Poor operational practise
NATURE 2K -- Animal waste/slurry
Comments: NO SITES DOWNSTREAM. RUNOFF FROM FIELD TO FARM LANE TO BROOK. DISCHARGE ABOUT 4 HOURS.

Catch 048 SITE NR06.0401 URN R04B001 RECNO 120
DATE 20/10/92
RIVER (TRIB) OTTER
NAME CHURCHINFORD STW
PILS Number 62006220 POLLNGR ST22201250 CATEGORY 2
LENGTHAFF 0.25 Sample N Likelihood? U
Incident Description
ORIGIN 4A -- SW STW
CAUSE 6 -- Effluent discharge
REASON 6 -- Poor management control
NATURE 2B -- Treated Sewage Effluent
Comments: SITES 2.5 KM D/S. VISIBLE SEWAGE FUNGUS IN

Catch 048 SITE NR06.0403 URN R04B003 RECNO 113
DATE 25/08/92
RIVER (TRIB) OTTER
NAME CROSSHILLS FARM, WESTON, HONITON
PILS Number 62006207 POLLNGR ST14400030 CATEGORY 2
LENGTHAFF 0.50 Sample Y Likelihood? A
Incident Description
ORIGIN 3A -- Cattle slurry store
CAUSE 5 -- Collapse
REASON 2 -- Accident
NATURE 2K -- Animal waste/slurry
Comments: 200 GALS SLURRY

Catch 048 SITE NR06.0406 URN R04B007 RECNO 148
DATE 10/12/92
RIVER OTTERTON BROOK AND OTTER
NAME WIMPY GOETECH LTD, OTTERTON
PILS Number 62007633 POLLNGR SY08208525 CATEGORY 1
LENGTHAFF 1.50 Sample Y Likelihood? A
Incident Description
ORIGIN 22 -- Industrial premises - Other
CAUSE 8 -- Direct discharge
REASON 5 -- Poor operational practise
NATURE 4K -- Quarry/extraction water
Comments: SUSPENDED SOLIDS.

Catch 048 SITE NR06.0409 URN R04B011 RECNO 112
DATE 16/08/92
RIVER WOLF
NAME LOSSES FARM, AWLISCOMBE
PILS Number 62007056 POLLNGR ST13400170 CATEGORY 1
LENGTHAFF 2.00 Sample Y Likelihood? A
Incident Description
ORIGIN 3A -- Cattle slurry store
CAUSE 3 -- Overflow
REASON 6 -- Poor management control
NATURE 2K -- Animal waste/slurry
Comments: 4,000 GALS SLURRY. FISH KILL: 24 TROUT. 48 HOUR DELAY IN REPORTING.

Catch 048 SITE NR06.0419 URN R04B024 RECNO 56
DATE 20/12/91
RIVER GITTISHAM STREAM
NAME COOMBE FARM, GITTISHAM
PILS Number 31001518 POLLNGR SY14209690 CATEGORY 1
LENGTHAFF 2.00 Sample Y Likelihood? A
Incident Description
ORIGIN 3C -- Cattle yard
CAUSE 9 -- Runoff
REASON C -- Inadequate design/capacity
NATURE 2K -- Animal waste/slurry
Comments:

IDENTIFICATION OF POLLUTION INCIDENTS POTENTIALLY AFFECTING
ROUTINE MONITORING SITES 1991 - 1992

Page No. 4
18/06/93

Catch 05A SITE NR06. URN RECNO 161
DATE 05/08/92
RIVER TRIB EXE
NAME NUTWELL LODGE, LYMPSTONE
PILS Number 62006832 POLLNGR SX99008580 CATEGORY 1
LENGTHAFF 0.00 Sample N Likelihood?

Incident Description

ORIGIN 4B -- Works (private)
CAUSE 8 -- Direct discharge
REASON 6 -- Poor management control
NATURE 2B -- Treated Sewage Effluent

Comments: NO SITES DOWNSTREAM. DISCHARGE AT RATE OF 5.6 CUBIC METRES PER DAY. NO LIFE IN STREAM DUE TO PROLONGED DISCHARGE.

Catch 05A SITE NR06. URN R05A027 RECNO 138
DATE 16/09/92
RIVER DAWLISH WATER
NAME MR LEEMING, MTH LODGE CLOSE, DAWL.
PILS Number 62006214 POLLNGR SX95857655 CATEGORY 2
LENGTHAFF 0.00 Sample Y Likelihood? 8

Incident Description

ORIGIN 5A -- Surface water sewers
CAUSE B -- Deliberate introduction
REASON 3 -- Deliberate act
NATURE 3F -- Waste oil

Comments: ABOUT 10 LITRES WASTE OIL FROM VAN OIL CHANGE.

LENGTH AFFECTED NOT SPECIFIED.

Catch 05B SITE NR06.0569 URN R05B013 RECNO 110
DATE 10/08/92
RIVER AYLESBEARE STREAM
NAME AYLESBEARE STW
PILS Number 62006201 POLLNGR SY03609180 CATEGORY 1
LENGTHAFF 0.50 Sample Y Likelihood? U

Incident Description

ORIGIN 4A -- SWW STW
CAUSE 7 -- Storm water discharge
REASON 6 -- Poor management control
NATURE 2A -- Crude Sewage

Comments: FISH KILL. CRUDE SEWAGE DISCHARGED FOR 2 DAYS (8-10 AUG)

Catch 05C SITE NR06.0519 URN R05C007 RECNO 71
DATE 17/02/92
RIVER (LEAT AT CULLOMPTON) CULM
NAME UNKNOWN
PILS Number 31001910 POLLNGR ST02300750 CATEGORY 2
LENGTHAFF 1.00 Sample Y Likelihood? 8

Incident Description

ORIGIN 22 -- Industrial premises - Other
CAUSE 3 -- Overflow
REASON 4 -- Poor maintenance
NATURE 3F -- Waste oil

Comments: SITES 1.5 KM D/S. ABOUT 50 GALLONS DIESEL.

Catch 05C SITE NR06.0524 URN R05C017 RECNO 70
DATE 08/02/92
RIVER SPRATFORD STREAM
NAME LLOYD MAUNDER, WILLAND
PILS Number 62007335 POLLNGR ST02751120 CATEGORY 2
LENGTHAFF 0.10 Sample Y Likelihood? U

Incident Description

ORIGIN 2B -- Abattoirs
CAUSE 9 -- Runoff
REASON 2 -- Accident
NATURE 2J -- Industrial effluent

Comments: SITES ABOUT 2 KM D/S.

Catch 05C SITE NR06.0579 URN R05C042 RECNO 78
DATE 18/03/92
RIVER DUNKESWELL STREAM, MADFORD
NAME DUNKESWELL STW
PILS Number 31001924 POLLNGR ST14700800 CATEGORY 2
LENGTHAFF 2.00 Sample N Likelihood? A

Incident Description

ORIGIN 4A -- SWW STW
CAUSE 6 -- Effluent discharge
REASON E -- Treatment failure
NATURE 1X -- Other Chemical

Comments: DETERGENT FOAD OVER A PERIOD. OTHER SITE AFFECTED: 0527 (2 KM).

IDENTIFICATION OF POLLUTION INCIDENTS POTENTIALLY AFFECTING
ROUTINE MONITORING SITES 1991 - 1992

Page No. 5
18/06/93

Catch 05D SITE NR06.0582 URN R05D002 RECNO 139
DATE 20/09/92
RIVER (PINES LEAT) EXE
NAME PINES WTW
PILS Number 62006133 POLLNGR SX93009720 CATEGORY 1
LENGTHAFF 0.50 Sample Y Likelihood? U
Incident Description
ORIGIN AA -- Water Treatment Works
CAUSE 1 -- Leakage
REASON D -- Mechanical/electrical plant failure
NATURE 1C -- Alkali
Comments: POLLUTION EFFECT RESTRICTED TO LEAT. FISH KILL: OVER 1,000 MAINLY CYPRINIDS. EXE NOT AFFECTED DUE TO MASSIVE DILUTION.

Catch 05D SITE NR06.0532 URN R05D004 RECNO 43
DATE 22/08/91
RIVER EXE VIA STORM DRAIN
NAME FLOWER POT LANE, EXETER
PILS Number 62002D12 POLLNGR SX91509240 CATEGORY 2
LENGTHAFF 0.40 Sample N Likelihood? U
Incident Description
ORIGIN SE -- Sewerage private
CAUSE 8 -- Direct discharge
REASON 6 -- Poor management control
NATURE 3D -- Hydraulic oil
Comments: 5 LTRS OIL BASED PAINT (SEEN OPPOSITE MILL ON EXE). SITES 1.5KM D/S ON EXE.

Catch 05E SITE NR06.0537 URN R05E004 RECNO 124
DATE 10/11/92
RIVER EXE
NAME SLUDGE TANKER OVERTURNED, TIVERTON
PILS Number 62007934 POLLNGR SS95201380 CATEGORY 2
LENGTHAFF 0.00 Sample N Likelihood? U
Incident Description
ORIGIN 1B -- Public highway - Road accident
CAUSE 1 -- Leakage
REASON 2 -- Accident
NATURE 2G -- Other sludge
Comments: SITES 1 KM D/S. 200 GALLONS INTO DRAINAGE DITCH. POLLUTION WELL CONTAINED.

Catch 05E SITE NR06.0542 URN R05E008 RECNO 119
DATE 14/10/92
RIVER IRONMILL STREAM
NAME BLINDWELL FARM, RACKENFORD
PILS Number 62007846 POLLNGR SS86701950 CATEGORY 1
LENGTHAFF 3.00 Sample Y Likelihood? B
Incident Description
ORIGIN 3A -- Cattle slurry store
CAUSE 3 -- Overflow
REASON 5 -- Poor operational practise
NATURE 2K -- Animal waste/slurry
Comments: ABOUT 750 GALLONS FARM WASTE. FISH FARM D/S AFFECTED. BIOLOGY SITE ABOUT 2.5 KM D/S, CHEMISTRY SITE A FURTHER 2 KM D/S.

Catch 05E SITE NR06.0537 URN R05E020 RECNO 67
DATE 01/02/92
RIVER CALVERLEIGH STREAM, EXE
NAME LOXBEARE BARTON, LOXBEARE
PILS Number 31001909 POLLNGR SS91301580 CATEGORY 1
LENGTHAFF 4.00 Sample Y Likelihood? U
Incident Description
ORIGIN 3A -- Cattle slurry store
CAUSE 3 -- Overflow
REASON C -- Inadequate design/capacity
NATURE 2K -- Animal waste/slurry
Comments: CHEM SITE R05E020 5 KM D/S ON CALVERLEIGH. SITE 0537 6 KM D/S ON EXE.

Catch 05G SITE NR06.0554 URN R05H003 RECNO 28
DATE 05/07/91
RIVER (TRIB) BARLE
NAME NORTHCOMBE FARM, DULVERTON
PILS Number 62000907 POLLNGR SS91502920 CATEGORY 2
LENGTHAFF 6.00 Sample N Likelihood? A
Incident Description
ORIGIN 3M -- Sheep dip
CAUSE 6 -- Effluent discharge
REASON 5 -- Poor operational practise
NATURE 1E -- Pesticide/Insecticide
Comments: 200 GALLONS SHEEP DIP EFFLUENT EMPTIED INTO POND WHICH OVERFLOWED TO TRIB BARLE.

IDENTIFICATION OF POLLUTION INCIDENTS POTENTIALLY AFFECTING
ROUTINE MONITORING SITES 1991 - 1992

Page No. 6
18/06/93

Catch 05J SITE NR06.0558 URN R05J002 RECNO 76
DATE 15/03/92
RIVER (TRIB) CREEDY
NAME TOWN BARTON FARM, SANDFORD
PILS Number 62006752 POLLNGR SS82700260 CATEGORY 2
LENGTHAFF 0.75 Sample Y Likelihood? U
Incident Description
ORIGIN 3V -- Spraying to land (Land runoff)
CAUSE 9 -- Runoff
REASON 6 -- Poor management control
NATURE 2K -- Animal waste/slurry
Comments: SITES 4 KM D/S. MINIMAL EFFECT ON CREEDY.

Catch 05J SITE NR06.0559 URN R05J016 RECNO 87
DATE 01/05/92
RIVER (BINNEFORD WATER) CREEDY
NAME MOOR FARM, BLACK DOG, CREDITON
PILS Number 62006748 POLLNGR SS81300870 CATEGORY 1
LENGTHAFF 3.00 Sample Y Likelihood? U
Incident Description
ORIGIN 3A -- Cattle slurry store
CAUSE 6 -- Effluent discharge
REASON C -- Inadequate design/capacity
NATURE 2K -- Animal waste/slurry
Comments: SITES 4 KM D/S

Catch 05J SITE NR06.0599 URN R05J016 RECNO 145
DATE 08/12/92
RIVER (TRIB) BINNERFORD WATER
NAME MOOR FARM, BLACKDOG, CREDITON
PILS Number 62008801 POLLNGR SS81300870 CATEGORY 2
LENGTHAFF 1.50 Sample Y Likelihood? A
Incident Description
ORIGIN 3A -- Cattle slurry store
CAUSE 1 -- Leakage
REASON 5 -- Poor operational practise
NATURE 2K -- Animal waste/slurry
Comments: SLURRY LAGOON OVERFLOWED DUE TO BLOCKED DRAINS. FUNGUS VISIBLE 500 M.

Catch 05J SITE NR06.0597 URN R05J017 RECNO 101
DATE 27/06/92
RIVER (TRIB) SHOBROOKE LAKE
NAME WESTFORDE FARM, CHERITON FITZ. CRED
PILS Number 62006585 POLLNGR SS87800530 CATEGORY 2
LENGTHAFF 2.00 Sample Y Likelihood? U
Incident Description
ORIGIN 3A -- Cattle slurry store
CAUSE 2 -- Spillage
REASON 2 -- Accident
NATURE 2K -- Animal waste/slurry
Comments: NEAREST D/S SITES 6 KM. 2,000 GALS DIRTY WATER AND SILAGE EFFLUENT. SMALL FISH KILL.

Catch 06A SITE NR06. URN RECNO 153
DATE 07/08/91
RIVER LEAT KINGSTEIGNTON TO TEIGN EST.
NAME SWW DEPOT, NEWTON ABBOT
PILS Number 62002816 POLLNGR Y CATEGORY 2
LENGTHAFF 0.40 Sample N Likelihood?
Incident Description
ORIGIN 5H -- Sewer pumping station private
CAUSE 3 -- Overflow
REASON 6 -- Poor management control
NATURE 2A -- Crude Sewage
Comments: NO SITES DOWNSTREAM

Catch 06A SITE NR06. URN RECNO 166
DATE 22/10/92
RIVER TRIB TEIGN ESTUARY
NAME STUDIO SCREENPRINTS, BROADHEAD. I.E
PILS Number 62007927 POLLNGR SX92807310 CATEGORY 2
LENGTHAFF 0.00 Sample N Likelihood?
Incident Description
ORIGIN 2C -- Paper and printing
CAUSE 6 -- Effluent discharge
REASON C -- Inadequate design/capacity
NATURE 1A -- Organic Chemical
Comments: NO SITES DOWNSTREAM. DISCHARGE VIA PIPE TO STORM WATER SEWER.

IDENTIFICATION OF POLLUTION INCIDENTS POTENTIALLY AFFECTING
ROUTINE MONITORING SITES 1991 - 1992

Page No. 7
18/06/93

Catch 06A SITE NR06.0601 URN R06A001 RECNO 22
DATE 10/06/91
RIVER ALLER BROOK
NAME EDGINSWELL PUMPING STATION
PILS Number 62002636 POLLNGR SX88206630 CATEGORY 1
LENGTHAFF 3.00 Sample N Likelihood? A
Incident Description
ORIGIN 5F -- Sewer pumping station Plc
CAUSE 3 -- Overflow
REASON 2 -- Other reasons for incident
NATURE 2A -- Crude Sewage
Comments: FISH KILL. BLOCKAGE IN SEWER AT PUMPING STATION CAUSED BY GARDEN WASTE.

Catch 06A SITE NR06.0602 URN R06A003 RECNO 103
DATE 03/07/92
RIVER (BEERS BROOK) ALLER BROOK
NAME COFFINSWELL STW
PILS Number 62006369 POLLNGR SX89006840 CATEGORY 2
LENGTHAFF 0.00 Sample Y Likelihood? B
Incident Description
ORIGIN 4A -- SWW STW
CAUSE 6 -- Effluent discharge
REASON D -- Mechanical/electrical plant failure
NATURE 2B -- Treated Sewage Effluent
Comments: AFFECTED LENGTH NOT SPECIFIED. SITES JUST D/S CONFLUENCE ALLER. SHEEP MORTALITY.

Catch 06B SITE NR06.0601 URN R06B001 RECNO 57
DATE 21/10/91
RIVER TEIGN
NAME WATTS BLAKE BEARNE,STH ACRE QUARRY
PILS Number 62002851 POLLNGR SX85207480 CATEGORY 1
LENGTHAFF 2.00 Sample Y Likelihood? B
Incident Description
ORIGIN 9L -- Cement & Lime works
CAUSE 1 -- Leakage
REASON 5 -- Poor operational practise
NATURE 3F -- Waste oil
Comments: OTHER SITES POSSIBLY AFFECTED: R06B013/0604. FEW HUNDRED GALLONS DIESEL OIL.

Catch 06B SITE NR06.0606 URN R06B005 RECNO 55
DATE 13/12/91
RIVER (TRIB) LEMON
NAME SEALE HAYNE FARM, NEWTON ABBOT
PILS Number 62007008 POLLNGR SX82707310 CATEGORY 2
LENGTHAFF 3.00 Sample Y Likelihood? B
Incident Description
ORIGIN 3A -- Cattle slurry store
CAUSE 4 -- Burst
REASON X -- Unknown
NATURE 2K -- Animal waste/slurry
Comments: 10,000 GALLONS SLURRY.

Catch 06B SITE NR06.0605 URN R06B050 RECNO 31
DATE 17/07/91
RIVER LIVERTON BROOK (VIA EMERGENCY O/FL)
NAME SUMMERHILLS SEWAGE PUMPING STATION
PILS Number 62002789 POLLNGR SX81707450 CATEGORY 2
LENGTHAFF 1.00 Sample Y Likelihood? U
Incident Description
ORIGIN 5H -- Sewer pumping station private
CAUSE 3 -- Overflow
REASON D -- Mechanical/electrical plant failure
NATURE 2A -- Crude Sewage
Comments: SITES 2.5KM D/S.

Catch 06B SITE NR06.0605 URN R06B050 RECNO 94
DATE 29/05/92
RIVER (TRIB) LIVERTON BROOK
NAME HARTFORD FARM, LIVERTON
PILS Number 62007199 POLLNGR SX81507430 CATEGORY 2
LENGTHAFF 1.00 Sample Y Likelihood? U
Incident Description
ORIGIN 3P -- Silage stores
CAUSE 1 -- Leakage
REASON C -- Inadequate design/capacity
NATURE 2H -- Silage liquor
Comments: SITES 3 KM D/S. SEWAGE FUNGUS ON TRIB BED.

IDENTIFICATION OF POLLUTION INCIDENTS POTENTIALLY AFFECTING
ROUTINE MONITORING SITES 1991 - 1992

Page No. 8
18/06/93

Catch 06C SITE NR06.0641 URN R06C052 RECNO 108
DATE 04/08/92
RIVER BLACKATON BROOK
NAME EAST WEEK FARM, SOUTH ZEAL
PILS Number 62006341 POLLNGR SX66509160 CATEGORY 1
LENGTHAFF 4.00 Sample Y Likelihood? A
Incident Description
ORIGIN 3A -- Cattle slurry store
CAUSE 1 -- Leakage
REASON Z -- Other reasons for incident
NATURE 2K -- Animal waste/slurry
Comments: 5,000 GALLONS FARM WASTE. MAJOR FISH KILL (1,000'S)

Catch 07A SITE NR06. URN RECNO 173
DATE 20/08/92
RIVER DART
NAME TOTNES STW
PILS Number 62006926 POLLNGR SX80756095 CATEGORY 2
LENGTHAFF 0.50 Sample Y Likelihood?
Incident Description
ORIGIN 4A -- SWW STW
CAUSE 6 -- Effluent discharge
REASON C -- Inadequate design/capacity
NATURE 2B -- Treated Sewage Effluent
Comments: NO SITES DOWNSTREAM.

Catch 07A SITE NR06. URN RECNO 174
DATE 27/11/92
RIVER MALT MILL LAKE AND DART
NAME FOLLATON HOUSE, TOTNES
PILS Number 62006950 POLLNGR SX78756050 CATEGORY 2
LENGTHAFF 1.00 Sample Y Likelihood?
Incident Description
ORIGIN 2F -- Building site
CAUSE 9 -- Runoff
REASON C -- Inadequate design/capacity
NATURE 4P -- Surface water
Comments: NO SITES DOWNSTREAM.

Catch 07A SITE NR06. URN RECNO 170
DATE 27/11/92
RIVER MALT MILL LAKE, R DART
NAME FOLLATON HOUSE, TOTNES
PILS Number 62006950 POLLNGR SX78756050 CATEGORY 2
LENGTHAFF 1.00 Sample Y Likelihood?
Incident Description
ORIGIN 2F -- Building site
CAUSE 9 -- Runoff
REASON C -- Inadequate design/capacity
NATURE 4P -- Surface water
Comments: NO SITES DOWNSTREAM. SUSPENDED SOLIDS.

Catch 07B SITE NR06. URN RECNO 151
DATE 13/05/91
RIVER DART
NAME TOTNES STW
PILS Number 62002346 POLLNGR SX81806090 CATEGORY 2
LENGTHAFF 0.00 Sample Y Likelihood?
Incident Description
ORIGIN 4A -- SWW STW
CAUSE 6 -- Effluent discharge
REASON E -- Treatment failure
NATURE 2B -- Treated Sewage Effluent
Comments: NO SITES DOWNSTREAM. FOAM AND SCUM AT TOTNES DURING MAY.

Catch 07B SITE NR06.0706 URN R07B017 RECNO 155
DATE 05/12/91
RIVER (TRIB) AM BROOK
NAME THE OLD GRANGE, BRIDGE ST, IPPLEPEN
PILS Number 31001508 POLLNGR SX83506680 CATEGORY 2
LENGTHAFF 0.00 Sample N Likelihood? U
Incident Description
ORIGIN 2A -- Dairies
CAUSE 4 -- Burst
REASON 4 -- Poor maintenance
NATURE 3F -- Waste oil
Comments: BROKEN UNDERGROUND PIPE. ABOUT 500 LTS CENTRAL HEATING OIL DISCHARGING FOR ABOUT 2 WEEKS. OVER 20 DEAD TROUT.

IDENTIFICATION OF POLLUTION INCIDENTS POTENTIALLY AFFECTING
ROUTINE MONITORING SITES 1991 - 1992

Page No. 9
18/06/93

Catch 07B SITE NR06.0706 URN R07B017 RECNO 135
DATE 05/12/91
RIVER (TR18) AM BROOK, HEMS
NAME THE OLD GRANGE, BRIDGE ST, IPPLEPEN
PILS Number 31001508 POLLNGR SX83506680 CATEGORY 2
LENGTHAFF 0.00 Sample M Likelihood? U

Incident Description

ORIGIN 2A -- Dairies
CAUSE 4 -- Burst
REASON 4 -- Poor maintenance
NATURE 3F -- Waste oil

Comments: SITES ABOUT 2 KM D/S. ABOUT 500 LITRES CENTRAL HEATING OIL FROM BROKEN UNDERGROUND PIPE -
DISCHARGING FOR 2 WEEKS. OVER 20 DEAD TROUT.

Catch 07B SITE NR06.0711 URN R07B019 RECNO 92
DATE 20/05/92
RIVER BIDWELL BROOK
NAME MANHOLE DARTINGTON
PILS Number 62006660 POLLNGR SX78506200 CATEGORY 1
LENGTHAFF 1.00 Sample Y Likelihood? B

Incident Description

ORIGIN 5D -- Sewerage Plc
CAUSE 6 -- Effluent discharge
REASON C -- Inadequate design/capacity
NATURE 2A -- Crude Sewage

Comments: SITES 1.5 KM D/S. THIRD OCCURANCE WITHIN ONE WEEK.

Catch 07B SITE NR06.0708 URN R07B052 RECNO 58
DATE 02/01/92
RIVER DEAN BURN
NAME SKERRATON FARM, BUCKFASTLEIGH
PILS Number 31001332 POLLNGR SX70806460 CATEGORY 2
LENGTHAFF 0.25 Sample Y Likelihood? U

Incident Description

ORIGIN 3A -- Cattle slurry store
CAUSE 4 -- Burst
REASON C -- Inadequate design/capacity
NATURE 2K -- Animal waste/slurry

Comments: SITES 2 KM D/S

Catch 07B SITE NR06.0728 URN R07B052 RECNO 52
DATE 10/11/91
RIVER DEAN BURN
NAME SKERRATON FARM, BUCKFASTLEIGH
PILS Number 31001332 POLLNGR SX70806460 CATEGORY 1
LENGTHAFF 4.00 Sample M Likelihood? A

Incident Description

ORIGIN 3A -- Cattle slurry store
CAUSE 6 -- Effluent discharge
REASON C -- Inadequate design/capacity
NATURE 2K -- Animal waste/slurry

Comments:

Catch 08A SITE NR06.0817 URN RECNO 38
DATE 09/08/91
RIVER CHILLINGTON STREAM VIA TR18
NAME COLERIDGE NURSING HOME, CHILLINGTON
PILS Number 62002770 POLLNGR SX79404380 CATEGORY 2
LENGTHAFF 0.50 Sample Y Likelihood? B

Incident Description

ORIGIN 2G -- Industrial premises - (Organic other)
CAUSE A -- Leachate
REASON C -- Inadequate design/capacity
NATURE 2A -- Crude Sewage

Comments: NO CHEMISTRY SITE. BIOLOGY SITE 1KM D/S. DOMESTIC SEWAGE.

Catch 08B SITE NR06. URN RECNO 157
DATE 01/03/92
RIVER TR18 AVON
NAME KNOWLE FARM, AVETON GIFFORD
PILS Number 62007023 POLLNGR SX67604875 CATEGORY 2
LENGTHAFF 0.50 Sample Y Likelihood?

Incident Description

ORIGIN 3W -- Farm drainage
CAUSE 3 -- Overflow
REASON C -- Inadequate design/capacity
NATURE 2K -- Animal waste/slurry

Comments: NO SITES DOWNSTREAM. STREAM BADLY AFFECTED BY FUNGAL GROWTH.

IDENTIFICATION OF POLLUTION INCIDENTS POTENTIALLY AFFECTING
ROUTINE MONITORING SITES 1991 - 1992

Page No. 10
18/06/93

Catch 088	SITE DATE RIVER NAME	NR06.0810 05/02/91 (CHARFORD BROOK), AVON WONTON FARM, AVONWICK, TOTNES	URN R08B003	RECNO 5	POLLNGR SX72755920 Likelihood? U	CATEGORY 2
	PILS Number LENGTHAFF	62001283 1.50	Sample Y			
Incident Description	ORIGIN	3A -- Cattle slurry store				
	CAUSE	3 -- Overflow				
	REASON	4 -- Poor maintenance				
	NATURE	2K -- Animal waste/slurry				
Comments: SITES 6KM D/S						
Catch 088	SITE DATE RIVER NAME	NR06.0810 02/07/91 (TRIB) AVON DIPTFORD DOWNS FM, DIPTFORD, TOTNES	URN R08B017	RECNO 27	POLLNGR SX73205750 Likelihood? U	CATEGORY 2
	PILS Number LENGTHAFF	62002751 0.50	Sample Y			
Incident Description	ORIGIN	3A -- Cattle slurry store				
	CAUSE	6 -- Effluent discharge				
	REASON	C -- Inadequate design/capacity				
	NATURE	2K -- Animal waste/slurry				
Comments: SITES 4 KM. FUNGAL GROWTH FOR 0.25 KM.						
Catch 088	SITE DATE RIVER NAME	NR06.0810 05/02/92 (CHARFORD BROOK) AVON WONTON FARM, AVONWICK	URN R98B003	RECNO 69	POLLNGR SX72755925 Likelihood? U	CATEGORY 2
	PILS Number LENGTHAFF	62007020 1.00	Sample Y			
Incident Description	ORIGIN	3V -- Spraying to land (Land runoff)				
	CAUSE	9 -- Runoff				
	REASON	6 -- Poor management control				
	NATURE	2K -- Animal waste/slurry				
Comments: SITES 7 KM D/S.						
Catch 09B	SITE DATE RIVER NAME	NR06.0902 10/02/91 ERME PIPELINE EXCAVATIONS	URN R09B010	RECNO 6	POLLNGR SX63805470 Likelihood? A	CATEGORY 2
	PILS Number LENGTHAFF	62001992 6.50	Sample Y			
Incident Description	ORIGIN	1D -- Public highway - Road construction/maintenance				
	CAUSE	4 -- Burst				
	REASON	X -- Unknown				
	NATURE	4P -- Surface water				
Comments: 6 INCH MAIN DISCHARGED EXCAVATIONS FOR 12 HOURS. OTHER SITES AFFECTED: R09B003/0903						
Catch 09B	SITE DATE RIVER NAME	NR06.0905 04/02/91 ERME WIGGINS TEAPE (FINE PAPERS) LTD	URN R09B012	RECNO 4	POLLNGR SX63605660 Likelihood? A	CATEGORY 2
	PILS Number LENGTHAFF	62001865 3.00	Sample Y			
Incident Description	ORIGIN	2F -- Building site				
	CAUSE	2 -- Spillage				
	REASON	5 -- Poor operational practise				
	NATURE	1X -- Other Chemical				
Comments: WATER TURNED BLUE DUE TO DISCHARGE OF TINOPAL ABP PAPER WHITENING AGENT.						
Catch 10A	SITE DATE RIVER NAME	NR06.0905 15/03/91 NOSS MAYO CREEK COULSTON FARM, NOSS MAYO	URN	RECNO 10	POLLNGR SX56804710 Likelihood? N	CATEGORY 2
	PILS Number LENGTHAFF	51001677 1.50	Sample Y			
Incident Description	ORIGIN	3S -- Mechanical plant/equipment				
	CAUSE	4 -- Burst				
	REASON	2 -- Accident				
	NATURE	2K -- Animal waste/slurry				
Comments: NO SITES D/S						

IDENTIFICATION OF POLLUTION INCIDENTS POTENTIALLY AFFECTING
ROUTINE MONITORING SITES 1991 - 1992

Page No. 11
18/06/93

Catch 10A SITE NR06. URN RECNO 154
DATE 14/08/91
RIVER YEALM
NAME TARMAC LTD, BRIXTON
PILS Number 62004103 POLLNGR SX54605040 CATEGORY 2
LENGTHAFF 2.00 Sample Y Likelihood?
Incident Description
ORIGIN 92 -- Other Mine/Quarry or Mineral industrial
CAUSE 8 -- Direct discharge
REASON 3 -- Deliberate act
NATURE 4K -- Quarry/extraction water
Comments: NO SITES DOWNSTREAM.

Catch 10B SITE NR06.1012 URN R10B005 RECNO 9
DATE 14/02/91
RIVER YEALM
NAME A MCFADDEN & CO, SHAUGH LAKE
PILS Number 51001597 POLLNGR SX58055176 CATEGORY 1
LENGTHAFF 4.00 Sample Y Likelihood? A
Incident Description
ORIGIN 62 -- Cross-country - other
CAUSE 8 -- Deliberate introduction
REASON 3 -- Deliberate act
NATURE 4H -- Solid waste
Comments: DISCOLOURATION

Catch 10B SITE NR06.1005 URN R10B008 RECNO 93
DATE 27/05/92
RIVER PIALL
NAME ECCI AT CHOLWICHTOWN TIP
PILS Number 62004468 POLLNGR SX59705950 CATEGORY 2
LENGTHAFF 2.00 Sample N Likelihood? A
Incident Description
ORIGIN 92 -- Other Mine/Quarry or Mineral industrial
CAUSE 8 -- Direct discharge
REASON 5 -- Poor operational practise
NATURE 1J -- Alum
Comments: HUNDREDS OF DEAD FISH. SITES 2 KM D/S.

Catch 11A SITE NR06.1107 URN R11A002 RECNO 95
DATE 30/05/92
RIVER TORY BROOK
NAME ECCI, LEE MOOR
PILS Number 62004396 POLLNGR SX57006085 CATEGORY 2
LENGTHAFF 6.00 Sample N Likelihood? A
Incident Description
ORIGIN 9A -- China clay works
CAUSE 4 -- Burst
REASON 2 -- Accident
NATURE 4N -- Process water
Comments: SITE 0.5 KM D/S. 6,000 GALS CHINA CLAY PROCESS WATER.

Catch 11B SITE NR06.1104 URN R11B006 RECNO 45
DATE 01/09/91
RIVER (TRIB) PLYM
NAME COMMONWOOD COTT. ESTOVER, PLYMOUTH
PILS Number 62004123 POLLNGR SX51706030 CATEGORY 2
LENGTHAFF 1.50 Sample Y Likelihood? B
Incident Description
ORIGIN 5A -- Surface water sewers
CAUSE 8 -- Direct discharge
REASON 6 -- Poor management control
NATURE 3A -- Diesel
Comments: SITES 1.5KM D/S. WHITE FOAM.

Catch 12A SITE NR06. URN RECNO 160
DATE 15/04/92
RIVER LATCHBROOK LEAT, FORDER LAKE
NAME K HODGE LTD, BURRATON
PILS Number 62004457 POLLNGR SX40605970 CATEGORY 2
LENGTHAFF 2.00 Sample Y Likelihood?
Incident Description
ORIGIN 10 -- Public highway - Road construction/maintenance
CAUSE 2 -- Other cause of incident
REASON 5 -- Poor operational practise
NATURE 4Z -- Other
Comments: NO SITES DOWNSTREAM

IDENTIFICATION OF POLLUTION INCIDENTS POTENTIALLY AFFECTING
ROUTINE MONITORING SITES 1991 - 1992

Page No. 12
18/06/93

Catch 12A SITE NR06. URN RECNO 164
DATE 14/09/92
RIVER TRIB TIDDY VIA DRAINS AND PONDS
NAME ROAD ACCIDENT FUEL BOWSER
PILS Number 62005201 POLLNGR SX36506020 CATEGORY 2
LENGTHAFF 0.00 Sample Y Likelihood?
Incident Description
ORIGIN 1B -- Public highway - Road accident
CAUSE 1 -- Leakage
REASON 2 -- Accident
NATURE 3A -- Diesel
Comments: ABOUT 4,000 LTS RED DIESEL ON A38. ABOUT 50 DUCKS TREATED BY RSPB.

Catch 12B SITE NR06. URN RECNO 159
DATE 23/07/92
RIVER TRIB TAMAR
NAME DOMAINE LEISURE, CALLINGTON
PILS Number 41001981 POLLNGR SX41407030 CATEGORY 2
LENGTHAFF 0.00 Sample Y Likelihood?
Incident Description
ORIGIN 4B -- Works (private)
CAUSE 8 -- Direct discharge
REASON E -- Treatment failure
NATURE 2B -- Treated Sewage Effluent
Comments: NO SITES DOWNSTREAM

Catch 12C SITE NR06.1206 URN R12C010 RECNO 14
DATE 02/04/91
RIVER LUMBURN
NAME WOODOVIS FARM, LAMERTON, TAVISTOCK
PILS Number 41001517 POLLNGR SX43257505 CATEGORY 2
LENGTHAFF 4.50 Sample Y Likelihood? B
Incident Description
ORIGIN 3A -- Cattle slurry store
CAUSE 3 -- Overflow
REASON 6 -- Poor management control
NATURE 2K -- Animal waste/slurry
Comments: SITES 4.5KM D/S

Catch 12E SITE NR06.1214 URN R12E001 RECNO 11
DATE 19/03/91
RIVER (TRIB) TAMAR
NAME HEXWORTHY BARTON, LAUNCESTON
PILS Number 41001487 POLLNGR SX35708090 CATEGORY 2
LENGTHAFF 1.00 Sample Y Likelihood? A
Incident Description
ORIGIN 3F -- Cattle slurry treatment plant
CAUSE 3 -- Overflow
REASON D -- Mechanical/electrical plant failure
NATURE 2K -- Animal waste/slurry
Comments:

Catch 12F SITE NR06.1223 URN R12F002 RECNO 105
DATE 22/07/92
RIVER LYD
NAME AMBROSIA CPC, LIFTON
PILS Number 62005051 POLLNGR SX39608510 CATEGORY 2
LENGTHAFF 0.00 Sample N Likelihood? B
Incident Description
ORIGIN 2A -- Dairies
CAUSE 6 -- Effluent discharge
REASON X -- Unknown
NATURE 22 -- Other trade effluent
Comments: LENGTH AFFECTED NOT SPECIFIED.

Catch 12F SITE NR06.1223 URN R12F002 RECNO 118
DATE 13/10/92
RIVER LYD
NAME AMBROSIA LTD, LIFTON
PILS Number 62005043 POLLNGR SX39708500 CATEGORY 1
LENGTHAFF 3.50 Sample N Likelihood? A
Incident Description
ORIGIN 2A -- Dairies
CAUSE 4 -- Burst
REASON C -- Inadequate design/capacity
NATURE 1C -- Alkali
Comments: ABOUT 500 GALLONS CHLORINE/CAUSTIC. LARGE FISH KILL.

Catch 12G SITE NR06.1228 URN R12G001 RECNO 81
DATE 04/04/92
RIVER THRUSHEL
NAME TARMAC CONSTRUCTION, SOURTON CROSS
PILS Number 41001844 POLLNGR SX53609160 CATEGORY 2
LENGTHAFF 2.00 Sample M Likelihood? U
Incident Description
ORIGIN 1D -- Public highway - Road construction/maintenance
CAUSE A -- Leachate
REASON 6 -- Poor management control
NATURE 4P -- Surface water
Comments: SITES 5 KM D/S.

Catch 12G SITE NR06.1228 URN R12G001 RECNO 85
DATE 24/04/92
RIVER (TRIB) THRUSHEL
NAME TARMAC CONSTRUCTION, SOURTON CROSS
PILS Number 41001887 POLLNGR SX52709150 CATEGORY 2
LENGTHAFF 1.50 Sample M Likelihood? U
Incident Description
ORIGIN 1D -- Public highway - Road construction/maintenance
CAUSE 9 -- Runoff
REASON 6 -- Poor management control
NATURE 4P -- Surface water
Comments: SITES 3.5 KM D/S.

Catch 12G SITE NR06.1228 URN R12G001 RECNO 97
DATE 01/06/92
RIVER (WEEK) THRUSHEL
NAME TARMAC CONSTRUCTION, SOURTON CROSS
PILS Number 41001898 POLLNGR SX52709150 CATEGORY 2
LENGTHAFF 6.00 Sample Y Likelihood? A
Incident Description
ORIGIN 1D -- Public highway - Road construction/maintenance
CAUSE 9 -- Runoff
REASON 6 -- Poor management control
NATURE 4P -- Surface water
Comments: LOCAL FISHING AFFECTED.

Catch 12G SITE NR06.1233 URN R12G005 RECNO 142
DATE 18/09/92
RIVER TRIB WOLF
NAME COOMBE FARM, BEAUFORTHY
PILS Number 62005032 POLLNGR SX45309650 CATEGORY 1
LENGTHAFF 3.00 Sample Y Likelihood? A
Incident Description
ORIGIN 3L -- Poultry yard/battery
CAUSE 3 -- Overflow
REASON C -- Inadequate design/capacity
NATURE 2K -- Animal waste/slurry
Comments: OVERFLOW OF DIRTY WATER TO LAGOON TO LAND DRAINAGE. CONSIDERABLE FUNGAL GROWTH D/S.

Catch 12G SITE NR06.1299 URN R12G006 RECNO 2
DATE 17/01/91
RIVER WOLF
NAME ROADFORD FORESTRY OPERATIONS
PILS Number 41001457 POLLNGR SX41708920 CATEGORY 2
LENGTHAFF 4.00 Sample Y Likelihood? A
Incident Description
ORIGIN 3Z -- Farm premises/land other
CAUSE 9 -- Runoff
REASON 5 -- Poor operational practise
NATURE 4P -- Surface water
Comments: DISCOLORATION. FISHERY INTERESTS AFFECTED.

Catch 12G SITE NR06.1234 URN R12G007 RECNO 115
DATE 27/08/92
RIVER (BREWERS TRIB) WOLF
NAME TARMAC CONSTRUCTION, BREWER
PILS Number 41001997 POLLNGR SX41408840 CATEGORY 2
LENGTHAFF 1.50 Sample Y Likelihood? U
Incident Description
ORIGIN 1D -- Public highway - Road construction/maintenance
CAUSE 9 -- Runoff
REASON 5 -- Poor operational practise
NATURE 4P -- Surface water
Comments: SITES ABOUT 3 KM D/S. SUSPENDED SOLIDS. LOCAL FISHING AND FISH FARM AFFECTED.

IDENTIFICATION OF POLLUTION INCIDENTS POTENTIALLY AFFECTING
ROUTINE MONITORING SITES 1991 - 1992

Page No. 14
18/06/93

Catch 12G SITE NR06.1232 URN R12G010 RECNO 116
DATE 28/08/92
RIVER BREAZLE WATER
NAME TARMAC CONSTRUCTION
PILS Number 41001998 POLLNGR SX44808910 CATEGORY 2
LENGTHAFF 0.50 Sample Y Likelihood? A
Incident Description
ORIGIN 1D -- Public highway - Road construction/maintenance
CAUSE 9 -- Runoff
REASON 3 -- Deliberate act
NATURE 4P -- Surface water

Comments:

Catch 12G SITE NR06.1235 URN R12G012 RECNO 82
DATE 09/04/92
RIVER BROADWOOD BROOK
NAME UPOTT BARTON, BROADWOODWIDGER
PILS Number 41001850 POLLNGR SX39809050 CATEGORY 2
LENGTHAFF 1.00 Sample N Likelihood? U
Incident Description
ORIGIN 3V -- Spraying to land (Land runoff)
CAUSE A -- Leachate
REASON 6 -- Poor management control
NATURE 2K -- Animal waste/slurry

Comments: SITES 2.5 KM D/S

Catch 12H SITE NR06.5203 URN R12H008 RECNO 49
DATE 21/10/91
RIVER (TRIB) CAREY
NAME PANSON FM, ST GILES IN THE HEATH
PILS Number 41001677 POLLNGR SX36109240 CATEGORY 2
LENGTHAFF 1.00 Sample Y Likelihood? U
Incident Description
ORIGIN 3C -- Cattle yard
CAUSE 6 -- Effluent discharge
REASON 3 -- Deliberate act
NATURE 2K -- Animal waste/slurry

Comments: SITES 4KM D/S.

Catch 12J SITE NR06.5204 URN R12J001 RECNO 68
DATE 05/02/92
RIVER (TRIB) TAMAR
NAME TETCOTT BARTON, TETCOTT, HOLSWORTHY
PILS Number 41001766 POLLNGR SX33229674 CATEGORY 2
LENGTHAFF 5.00 Sample Y Likelihood? B
Incident Description
ORIGIN 3A -- Cattle slurry store
CAUSE 4 -- Burst
REASON 6 -- Poor management control
NATURE 2K -- Animal waste/slurry

Comments: SITES JUST OVER 5 KM D/S ON TAMAR. 17,000 GALLONS FARM WASTE TO TRIB.

Catch 12K SITE NR06.1242 URN R12K002 RECNO 130
DATE 11/04/91
RIVER (TRIB) CLAW
NAME HEGGADON FARM, CLAWTON, HOLSWORTHY
PILS Number 41001766 POLLNGR SX37409900 CATEGORY 2
LENGTHAFF 8.00 Sample Y Likelihood? A
Incident Description
ORIGIN 3A -- Cattle slurry store
CAUSE 1 -- Leakage
REASON 2 -- Accident
NATURE 2K -- Animal waste/slurry

Comments: ABOUT 30,000 GALLONS SLURRY. FISHERIES/CONSERVATION AFFECTED.

Catch 12K SITE NR06.1242 URN R12K002 RECNO 152
DATE 11/04/91
RIVER (TRIB) CLAW
NAME HEGGADON FARM, HOLSWORTHY, CLAWTON
PILS Number 41001766 POLLNGR SX37409900 CATEGORY 2
LENGTHAFF 8.00 Sample Y Likelihood? A
Incident Description
ORIGIN 3A -- Cattle slurry store
CAUSE 1 -- Leakage
REASON 2 -- Accident
NATURE 2K -- Animal waste/slurry

Comments: ABOUT 30,000 GALLONS SLURRY. FISHERIES/CONSERVATION AFFECTED.

IDENTIFICATION OF POLLUTION INCIDENTS POTENTIALLY AFFECTING
ROUTINE MONITORING SITES 1991 - 1992

Page No. 15
18/06/93

Catch 12K SITE NR06.1242 URN R12K002 RECNO 121
DATE 28/10/92
RIVER (TRIB) CLAW
NAME SWINGDON FARM, ASHWATER, BEAWORTHY
PILS Number POLLNGR SX37289860 CATEGORY 2
LENGTHAFF 1.50 Sample Y Likelihood? U
Incident Description
ORIGIN 3V -- Spraying to land (Lend runoff)
CAUSE 9 -- Runoff
REASON 7 -- Weather
NATURE 2K -- Animal waste/slurry
Comments: SITES ABOUT 4 KM D/S.

Catch 12L SITE NR06.5215 URN R12L003 RECNO 146
DATE 09/12/92
RIVER TRIB TAMAR
NAME THORNE FARM, WHITSTONE
PILS Number POLLNGR SX27509930 CATEGORY 2
LENGTHAFF 0.15 Sample Y Likelihood? U
Incident Description
ORIGIN 3A -- Cattle slurry store
CAUSE 3 -- Overflow
REASON 7 -- Weather
NATURE 2K -- Animal waste/slurry
Comments: SITES ABOUT 1.5 KM D/S.

Catch 12L SITE NR06.1247 URN R12L006 RECNO 25
DATE 23/06/91
RIVER TAMAR HEADWATERS
NAME VIRWORTHY FARM, HOLSWORTHY
PILS Number POLLNGR SS31101020 CATEGORY 1
LENGTHAFF 16.00 Sample Y Likelihood? A
Incident Description
ORIGIN 3A -- Cattle slurry store
CAUSE 9 -- Runoff
REASON 5 -- Poor operational practise
NATURE 2K -- Animal waste/slurry
Comments: OTHER SITES R12L016/12113 4KM D/S. 20-70,000 GALLONS COW SLURRY (SLUICE GATE NOT PROPERLY CLOSED). LARGE FISH KILL(4000 approx).

Catch 12M SITE NR06.5218 URN R12M004 RECNO 111
DATE 14/08/92
RIVER (TRIB) OTTERY
NAME J KITTOU LTD, HALLWORTHY STOCKYARD
PILS Number POLLNGR SX18058799 CATEGORY 2
LENGTHAFF 1.00 Sample Y Likelihood? U
Incident Description
ORIGIN 2G -- Industrial premises - (Organic other)
CAUSE X -- Unknown
REASON X -- Unknown
NATURE 2Z -- Other trade effluent
Comments: SITES 5 KM D/S. MARKET/CATTLE WASTE VIA ROAD DRAINAGE TO TRIB.

Catch 12M SITE NR06.1257 URN R12M007 RECNO 51
DATE 07/11/91
RIVER (TRIB) OTTERY
NAME WERRINGTON PARK FARM, LAUNCESTON
PILS Number POLLNGR SX33658720 CATEGORY 2
LENGTHAFF 1.00 Sample Y Likelihood? A
Incident Description
ORIGIN 3N -- Silage effluent tank
CAUSE 6 -- Effluent discharge
REASON 6 -- Poor management control
NATURE 2H -- Silage liquor
Comments:

Catch 12M SITE NR06.5223 URN R12M008 RECNO 15
DATE 03/04/91
RIVER CANWORTHY WATER
NAME NEWHOUSE FARM, LAUNCESTON
PILS Number POLLNGR SX23459040 CATEGORY 2
LENGTHAFF 3.00 Sample Y Likelihood? A
Incident Description
ORIGIN 3E -- Cattle grazing land
CAUSE 4 -- Burst
REASON 5 -- Poor operational practise
NATURE 2K -- Animal waste/slurry
Comments:

IDENTIFICATION OF POLLUTION INCIDENTS POTENTIALLY AFFECTING
ROUTINE MONITORING SITES 1991 - 1992

Page No. 16
18/06/93

Catch 12M SITE NR06.5222 URN R12M010 RECNO 59
DATE 08/01/92
RIVER CAUDWORTHY WATER
NAME DELABOLE FARM, WEEK ST MARY
PILS Number 41001752 POLLNGR SX23329595 CATEGORY 2
LENGTHAFF 1.00 Sample Y Likelihood? U
Incident Description
ORIGIN 3C -- Cattle yard
CAUSE 6 -- Effluent discharge
REASON 3 -- Deliberate act
NATURE 2K -- Animal waste/slurry
Comments: SITES 5 KM D/S.

Catch 12M SITE NR06.5222 URN R12M010 RECNO 60
DATE 14/01/92
RIVER (TRIB) CAUDWORTHY WATER
NAME BRAY & ROWE, MAXWORTHY FARM
PILS Number 41001756 POLLNGR SX25609300 CATEGORY 2
LENGTHAFF 0.50 Sample Y Likelihood? B
Incident Description
ORIGIN 3C -- Cattle yard
CAUSE 6 -- Effluent discharge
REASON 6 -- Poor management control
NATURE 2H -- Silage liquor
Comments: SITES ABOUT 500 M D/S. LARGE AMOUNT OF SOLIDS.

Catch 12M SITE NR06.5222 URN R12M010 RECNO 61
DATE 14/01/92
RIVER (TRIB) CAUDWORTHY WATER
NAME T UGLOW, MAXWORTHY FARM
PILS Number 41001755 POLLNGR SX25609310 CATEGORY 2
LENGTHAFF 0.50 Sample Y Likelihood? B
Incident Description
ORIGIN 3P -- Silage stores
CAUSE 9 -- Runoff
REASON 6 -- Poor management control
NATURE 2H -- Silage liquor
Comments: SITES ABOUT 500 M D/S. FUNGUS AND STRONG SMELL.

Catch 12M SITE NR06.1259 URN R12M011 RECNO 131
DATE 02/07/91
RIVER CAUDWORTHY WATER (VIA FIELD DITCH)
NAME WINNACOTT FM, NTH PETHERWIN, LAUNC.
PILS Number 41001574 POLLNGR SX25209010 CATEGORY 2
LENGTHAFF 1.00 Sample Y Likelihood? B
Incident Description
ORIGIN 3A -- Cattle slurry store
CAUSE 3 -- Overflow
REASON 5 -- Poor operational practise
NATURE 2K -- Animal waste/slurry
Comments: SITES JUST OVER 1 KM D/S.

Catch 12P SITE NR06.1264 URN RECNO 41
DATE 16/08/91
RIVER (TRIB) INNY
NAME TREBULLETT FARM, LAUNCESTON
PILS Number 41001620 POLLNGR SX32407830 CATEGORY 2
LENGTHAFF 0.00 Sample Y Likelihood? B
Incident Description
ORIGIN 3P -- Silage stores
CAUSE 1 -- Leakage
REASON 5 -- Poor operational practise
NATURE 2H -- Silage liquor
Comments: LENGTH NOT SPECIFIED. FUNGUS IN STREAM BELOW FARM. NO CHEMISTRY SITE D/S.

Catch 12P SITE NR06.5228 URN R12P002 RECNO 88
DATE 07/05/92
RIVER (TRIB) INNY
NAME INNY VALE HOLIDAY VILL. DAVIDSTOWE
PILS Number 41001871 POLLNGR SX16008692 CATEGORY 2
LENGTHAFF 0.00 Sample Y Likelihood? B
Incident Description
ORIGIN 4B -- Works (private)
CAUSE 6 -- Effluent discharge
REASON 4 -- Poor maintenance
NATURE 2B -- Treated Sewage Effluent
Comments: LENGTH AFFECTED NOT SPECIFIED. SITES 1.5 KM D/S ON CREEDY.

IDENTIFICATION OF POLLUTION INCIDENTS POTENTIALLY AFFECTING
ROUTINE MONITORING SITES 1991 - 1992

Page No. 17
18/06/93

Catch 120 SITE NR06.5234 URN R120002 RECNO 86
DATE 28/04/92
RIVER LYNHER
NAME GLUBHOLE FM, NORTH HULL, LAUNCESTON
PILS Number 41001865 POLLNGR SX27157665 CATEGORY 2
LENGTHAFF 1.00 Sample Y Likelihood? A
Incident Description
ORIGIN 3A -- Cattle slurry store
CAUSE 6 -- Effluent discharge
REASON 3 -- Deliberate act
NATURE 2X -- Animal waste/slurry
Comments:

Catch 120 SITE . URN R120003 RECNO 18
DATE 29/04/91
RIVER (TRIB) LYNHER
NAME KNOWLE FARM, UPTON CROSS, LISKEARD
PILS Number 4100155 POLLNGR SX27107270 CATEGORY 2
LENGTHAFF 3.00 Sample Y Likelihood? B
Incident Description
ORIGIN 3A -- Cattle slurry store
CAUSE 5 -- Collapse
REASON 6 -- Poor management control
NATURE 2K -- Animal waste/slurry
Comments: CHEMISTRY SITE 2 KM D/S. NEAREST BIOLOGY SITE 6 KM D/S.

Catch 120 SITE NR06.1268 URN R120003 RECNO 107
DATE 27/07/92
RIVER (TRIB) LYNHER
NAME BOTTERNELL FM, NORTH HILL, LAUNCES.
PILS Number 62004635 POLLNGR SX27857450 CATEGORY 2
LENGTHAFF 1.50 Sample Y Likelihood? U
Incident Description
ORIGIN 3P -- Silage stores
CAUSE 8 -- Direct discharge
REASON 5 -- Poor operational practise
NATURE 2H -- Silage liquor
Comments: SITES 3.5 KM D/S. 3 CUBIC M SILAGE LIQUOR.

Catch 120 SITE NR06.5235 URN R120004 RECNO 1
DATE 14/01/91
RIVER (trib) Lynher
NAME Polhilea, Collington
PILS Number 51001441 POLLNGR SX33707120 CATEGORY 2
LENGTHAFF 1.50 Sample Y Likelihood? B
Incident Description
ORIGIN 3P -- Silage stores
CAUSE A -- Leachate
REASON C -- Inadequate design/capacity
NATURE 2H -- Silage liquor
Comments:

Catch 148 SITE NR06.1402 URN RECNO 17
DATE 18/04/91
RIVER EAST LOOE RIVER
NAME ROSELAND AGREGATES, LEAM QY, LISK.
PILS Number 51001667 POLLNGR SX25106110 CATEGORY 2
LENGTHAFF 3.00 Sample Y Likelihood? A
Incident Description
ORIGIN 9N -- Other chemical
CAUSE 8 -- Direct discharge
REASON 5 -- Poor operational practise
NATURE 3C -- Petrol
Comments: SUSPENDED SOLIDS FROM QUARRY.

Catch 158 SITE NR06.1506 URN R158021 RECNO 143
DATE 30/09/92
RIVER (TRIB) CARDINHAM WATER
NAME ROAD ACCIDENT CARMINOW CROSS ROUND.
PILS Number 62005176 POLLNGR SX08806570 CATEGORY 2
LENGTHAFF 0.00 Sample N Likelihood? U
Incident Description
ORIGIN 1B -- Public highway - Road accident
CAUSE 2 -- Spillage
REASON 2 -- Accident
NATURE 4F -- Milk
Comments: MILKTANKER OVERTURNED CARMINOW CROSS ROUNDABOUT A30 BODMIN BYPASS. 11 CUBIC M MILK VIA ROAD DRAINAGE TO TRIB.

IDENTIFICATION OF POLLUTION INCIDENTS POTENTIALLY AFFECTING
ROUTINE MONITORING SITES 1991 - 1992

Page No. 18
18/06/93

Catch 16A SITE NR06.1605 URN R16A013 RECNO 64
DATE 20/01/92
RIVER TREVERBYN STREAM, PAR
NAME ECC1, PENWITHICK, ST AUSTELL
PILS Number 62003431 POLLNGR SX02855628 CATEGORY 2
LENGTHAFF 8.00 Sample Y Likelihood? A

Incident Description

ORIGIN 9C -- Metalliferous mine workings
CAUSE 4 -- Burst
REASON 2 -- Accident
NATURE 3A -- Diesel

Comments: OTHER SITES AFFECTED: R16A003/1609 (3.5KM PAR); R16A004/1602 (4.5 KM); R16A008/1610 (8 KM). FISH FARM D/S AFFECTED.

Catch 16A SITE NR06.1818 URN R18A021 RECNO 65
DATE 24/01/92
RIVER NEMBAL BROOK
NAME ECC1, BLACKPOOL DRYERS, ST AUSTELL
PILS Number 62003479 POLLNGR SW98255275 CATEGORY 2
LENGTHAFF 7.00 Sample Y Likelihood? A

Incident Description

ORIGIN 9C -- Metalliferous mine workings
CAUSE 4 -- Burst
REASON 2 -- Accident
NATURE 3A -- Diesel

Comments: 100 CUBIC M CHINA CLAY SLURRY.

Catch 17A SITE NR06.1703 URN R17A002 RECNO 54
DATE 06/12/91
RIVER CRINNIS
NAME WEST PHARMA, ST AUSTELL
PILS Number 62003479 POLLNGR SX03955275 CATEGORY 2
LENGTHAFF 2.50 Sample Y Likelihood? A

Incident Description

ORIGIN 2Z -- Industrial premises - Other
CAUSE B -- Deliberate introduction
REASON 6 -- Poor management control
NATURE 3F -- Waste oil

Comments: PROCESS WATER PERSISTENTLY DISCHARGED.

Catch 18A SITE NR06.1815 URN RECNO 90
DATE 11/05/92
RIVER HEWAS WATER
NAME DISUSED MINE ADIT
PILS Number 62005515 POLLNGR SW97874990 CATEGORY 2
LENGTHAFF 0.50 Sample N Likelihood? U

Incident Description

ORIGIN 9C -- Metalliferous mine workings
CAUSE 3 -- Overflow
REASON X -- Unknown
NATURE 4J -- Mining water

Comments: NEAREST D/S SITE 3 KM.

Catch 18A SITE NR06.1814 URN R18A001 RECNO 23
DATE 10/06/91
RIVER CAERHAYS STREAM
NAME PENGELLY FARM, HEWAS
PILS Number 62004006 POLLNGR SW96804920 CATEGORY 1
LENGTHAFF 2.00 Sample Y Likelihood? U

Incident Description

ORIGIN 3A -- Cattle slurry store
CAUSE 1 -- Leakage
REASON 4 -- Poor maintenance
NATURE 2H -- Silage liquor

Comments: SITES 4KM D/S. FISH KILL. INCIDENT CODE - 2H COMBINED WITH 2K (ANIMAL WASTE/SLURRY).

Catch 19A SITE NR06.1918 URN R19A016 RECNO 12
DATE 27/03/91
RIVER POLTESCO RIVER
NAME EGLOS FARM, HELSTON, RUAN MINOR
PILS Number 51001742 POLLNGR SW70601660 CATEGORY 1
LENGTHAFF 2.00 Sample Y Likelihood? B

Incident Description

ORIGIN 3A -- Cattle slurry store
CAUSE 8 -- Direct discharge
REASON 5 -- Poor operational practise
NATURE 2K -- Animal waste/slurry

Comments: SMALL FISH KILL. SITES 2.5KM D/S.

IDENTIFICATION OF POLLUTION INCIDENTS POTENTIALLY AFFECTING
ROUTINE MONITORING SITES 1991 - 1992

Page No. 19
18/06/93

Catch 19C SITE NR06.1925 URN R19C008 RECNO 63
DATE 17/01/92
RIVER (TRIB) GWINDRA STREAM
NAME ECCI, ST AUSTELL
PILS Number 62003430 POLLNGR 96465363 CATEGORY 2
LENGTHAFF 10.00 Sample Y Likelihood? A
Incident Description
ORIGIN 9C -- Metalliferous mine workings
CAUSE 4 -- Burst
REASON 2 -- Accident
NATURE 3A -- Diesel
Comments: 10 CUBIC M CHINA CLAY SLURRY

Catch 19C SITE NR06.1928 URN R19C016 RECNO 8
DATE 15/02/91
RIVER TREWITHEM STREAM
NAME TREVORVA FARM, PROBUS, TRURO
PILS Number 61001487 POLLNGR SW89904650 CATEGORY 2
LENGTHAFF 6.00 Sample Y Likelihood? A
Incident Description
ORIGIN 3A -- Cattle slurry store
CAUSE 2 -- Spillage
REASON 7 -- Weather
NATURE 2K -- Animal waste/slurry
Comments:

Catch 19C SITE NR06.1962 URN R19C017 RECNO 126
DATE 22/11/92
RIVER GWINDRA AND FAL
NAME ECCI, NANPEAN
PILS Number 62003741 POLLNGR SW95705540 CATEGORY 0
LENGTHAFF 5.00 Sample Y Likelihood? A
Incident Description
ORIGIN 6A -- Cross-country pipeline
CAUSE 4 -- Burst
REASON 2 -- Accident
NATURE 4N -- Process water
Comments: INFORMATION SAMPLES TAKEN OF DISCHARGE AND RIVER (GWINDRA). DISCOLOURED BY MICACEOUS RESIDUE AND CHINA CLAY WASTE. 19C NOT SAMPLED IN 1992.

Catch 19C SITE NR06. URN R19C021 RECNO 144
DATE 01/12/92
RIVER COOMBE STREAM
NAME DISUSED ADIT 450M U/S BRANNEL BRIDG
PILS Number 62005395 POLLNGR SW96105160 CATEGORY 2
LENGTHAFF 2.00 Sample Y Likelihood? A
Incident Description
ORIGIN 9C -- Metalliferous mine workings
CAUSE 3 -- Overflow
REASON 7 -- Weather
NATURE 4J -- Mining water
Comments: RIVERBED COATED, WATER COLOURED RED.

Catch 19D SITE NR06.1973 URN R19D015 RECNO 114
DATE 26/08/92
RIVER SHORLANESEND STREAM
NAME PENVALE FARM, SHORLANESEND, TRURO
PILS Number 62005132 POLLNGR SW80124734 CATEGORY 2
LENGTHAFF 0.10 Sample N Likelihood? B
Incident Description
ORIGIN 4C -- Septic tank
CAUSE 8 -- Direct discharge
REASON 3 -- Deliberate act
NATURE 2A -- Crude Sewage
Comments: SITES ABOUT 0.25 KM D/S. FISH KILL.

Catch 19E SITE NR06.1977 URN R19E003 RECNO 127
DATE 24/11/92
RIVER CARNON
NAME CARNON CONSOL., NANGILES ADIT DIS.
PILS Number 62003778 POLLNGR SW77504150 CATEGORY 2
LENGTHAFF 0.00 Sample N Likelihood? B
Incident Description
ORIGIN 9C -- Metalliferous mine workings
CAUSE 3 -- Overflow
REASON 7 -- Weather
NATURE 4J -- Mining water
Comments: DISCHARGE FROM ADIT INCREASED DUE TO HEAVY RAINFALL.

IDENTIFICATION OF POLLUTION INCIDENTS POTENTIALLY AFFECTING
ROUTINE MONITORING SITES 1991 - 1992

Page No. 20
18/06/93

Catch 19E SITE NR06.1945 URN R19E006 RECNO 125
DATE 18/11/92
RIVER KENNAL
NAME PENCOOSE FARM, STITHIANS
PILS Number 62003737 POLLNGR SW74503810 CATEGORY 2
LENGTHAFF 0.00 Sample N Likelihood? B
Incident Description
ORIGIN 3C -- Cattle yard
CAUSE 6 -- Effluent discharge
REASON 6 -- Poor management control
NATURE 2K -- Animal waste/slurry
Comments: BIOLOGY SITE 1.5 KM D/S, CHEMISTRY SITE 1 KM FURTHER D/S. LENGTH AFFECTED NOT SPECIFIED.

Catch 19E SITE NR06.1976 URN R19E015 RECNO 62
DATE 14/01/92
RIVER CARNOW
NAME CARNOW CONSOLIDATED LTD
PILS Number 61001814 POLLNGR SW76504170 CATEGORY 1
LENGTHAFF 8.00 Sample Y Likelihood? 0
Incident Description
ORIGIN 9C -- Metalliferous mine workings
CAUSE 4 -- Burst
REASON X -- Unknown
NATURE 4J -- Mining water
Comments: DISCOLOURATION DOWN TO FAL ESTUARY AND RESTORQUET CREEK.

Catch 20A SITE NR06.2008 URN RECNO 150
DATE 30/12/92
RIVER TOLCARNE STREAM (COBER)
NAME POLGEAR FARM, FOURLANES, REDRUTH
PILS Number 62003760 POLLNGR SW68303740 CATEGORY 1
LENGTHAFF 2.00 Sample Y Likelihood? B
Incident Description
ORIGIN 3C -- Cattle yard
CAUSE 6 -- Effluent discharge
REASON 6 -- Poor management control
NATURE 2K -- Animal waste/slurry
Comments: NO CHEMISTRY SITE D/S. DISCOLOURATION.

Catch 20A SITE NR06.2006 URN R20A009 RECNO 24
DATE 20/06/91
RIVER COBER (VIA SURFACE WATER DRAIN)
NAME HELSTON STW
PILS Number 61001575 POLLNGR SW65202670 CATEGORY 2
LENGTHAFF 2.00 Sample Y Likelihood? A
Incident Description
ORIGIN 4A -- SW STW
CAUSE 2 -- Spillage
REASON 5 -- Poor operational practise
NATURE 2E -- Sludge liquor
Comments: 3000 GALLONS UNTREATED SLUDGE DISCHARGED BY TANKER THROUGH PIPE TO LAND SURFACE WATER DRAIN.

Catch 21A SITE NR06. URN RECNO 165
DATE 02/10/92
RIVER LONGROCK STREAM
NAME PENRYN GRANITE, LUDGVAN, PENZANCE
PILS Number 62003713 POLLNGR SW49903140 CATEGORY 2
LENGTHAFF 2.00 Sample Y Likelihood?
Incident Description
ORIGIN 9G -- Quarrying
CAUSE 6 -- Effluent discharge
REASON 6 -- Poor management control
NATURE 4P -- Surface water
Comments: NO SITES DOWNSTREAM. SUSPENDED SOLIDS DISCHARGED AT 100 CUBIC M PER HOUR.

Catch 22A SITE - URN R22A012 RECNO 3
DATE 24/01/91
RIVER TREGASEAL STREAM
NAME JERICHO FARM, NEWBRIDGE, PENZANCE
PILS Number 61001450 POLLNGR SW39803170 CATEGORY 2
LENGTHAFF 1.50 Sample Y Likelihood? A
Incident Description
ORIGIN 3C -- Cattle yard
CAUSE 9 -- Runoff
REASON C -- Inadequate design/capacity
NATURE 2K -- Animal waste/slurry
Comments: NO BIOLOGY SITE WITHIN 4 KM D/S

Catch 22A SITE . URN R22A013 RECNO 46
DATE 02/09/91
RIVER STENNACK RIVER
NAME ST IVES MUSHROOMS LTD
PILS Number 61001737 POLLNGR SW50303870 CATEGORY 1
LENGTHAFF 0.75 Sample Y Likelihood? B
Incident Description
ORIGIN 2C -- Paper and printing
CAUSE 6 -- Effluent discharge
REASON 3 -- Deliberate act
NATURE 4M -- Process water
Comments: SITE 0.5KM D/S ON NORTH END OF BUSSOW RESERVOIR. NO BIOLOGY SITE D/S.

Catch 23A SITE NR06.2307 URN R23A007 RECNO 176
DATE 13/09/92
RIVER REEN STREAM, TRIB ROSEWORTHY STREAM
NAME SW AT CHYTODDEN FARM, TROOM
PILS Number 62005146 POLLNGR SW65903810 CATEGORY 2
LENGTHAFF 0.50 Sample Y Likelihood? U
Incident Description
ORIGIN 5B -- Sewer storm overflow Plc
CAUSE 3 -- Overflow
REASON C -- Inadequate design/capacity
NATURE 2A -- Crude Sewage
Comments: BLOCKED SEWER - STORM OVERFLOW

Catch 23A SITE NR06.2320 URN R23A042 RECNO 123
DATE 05/11/92
RIVER TEHIDY STREAM
NAME TEHIDY FARM PARK
PILS Number 62003731 POLLNGR SW67404130 CATEGORY 2
LENGTHAFF 0.00 Sample Y Likelihood? B
Incident Description
ORIGIN 22 -- Industrial premises - Other
CAUSE 2 -- Spillage
REASON 5 -- Poor operational practise
NATURE 4A -- Foam
Comments: LENGTH AFFECTED NOT SPECIFIED. 6 INCH HIGH FOAM ON TEHIDY STREAM AND ORNAMENTAL LAKE.

Catch 24A SITE NR06.2410 URN R24A008 RECNO 129
DATE 14/01/91
RIVER GANNEL
NAME PENHALE FARM, HIGHER FRADDON
PILS Number 61001451 POLLNGR SW90705750 CATEGORY 2
LENGTHAFF 3.00 Sample Y Likelihood? A
Incident Description
ORIGIN 3G -- Pig slurry store
CAUSE 9 -- Runoff
REASON 5 -- Poor operational practise
NATURE 2K -- Animal waste/slurry
Comments: SEWAGE FUNGUS FOUND.

Catch 25A SITE NR06.2527 URN R25A014 RECNO 44
DATE 31/08/91
RIVER MENALHYL HEADWATERS
NAME RETALLICK FARM, ST COLUMB
PILS Number 62004034 POLLNGR SW93856640 CATEGORY 2
LENGTHAFF 5.00 Sample Y Likelihood? A
Incident Description
ORIGIN 2F -- Building site
CAUSE B -- Deliberate introduction
REASON 6 -- Poor management control
NATURE 4D -- Vehicles
Comments: SUSPENDED SOLIDS. VEHICLES DRIVING THROUGH STREAM AND SKI JETS. SITES 2KM D/S. OTHER AFFECTED SITES: R25A001/2528 (4KM D/S).

Catch 25B SITE NR06.2541 URN R25B023 RECNO 132
DATE 05/07/91
RIVER (TRIB) CAMEL
NAME ST BREWARD SMO
PILS Number 62004028 POLLNGR SX09507650 CATEGORY 2
LENGTHAFF 1.00 Sample Y Likelihood? U
Incident Description
ORIGIN 5C -- Sewer storm overflow private
CAUSE 8 -- Direct discharge
REASON C -- Inadequate design/capacity
NATURE 2A -- Crude Sewage
Comments: SOLIDS DEPOSITED. LOCAL FISH PONDS AFFECTED.

Page No. 22
18/06/93

Catch 298	SITE	NRO6.2910	URN	R298039	RECNO	83
	DATE	21/04/92				
	RIVER	COMMON LAKE STREAM				
	NAME	NTH DEVON MEAT CO, TORRINGTON				
	PILS Number	62006760	POLLNGR	SS49301980	CATEGORY	2
	LENGTHAFF	2.00	Sample	Y	Likelihood?	A

Incident Description

L	ORIGIN	2B -- Abattoirs
	CAUSE	2 -- Other cause of incident
	REASON	6 -- Poor management control
	NATURE	2d -- Industrial effluent

Comments: TRADE WASTE DISCHARGED AT 5 LTRS PER SECOND.

Catch 298 SITE NR06.2910 URN R29B039 RECNO 109
DATE 10/08/92
RIVER COMMON LAKE STREAM
NAME SWSL AT TORRINGTON STW
PILS Number 62006698 POLLNGR SS50201930 CATEGORY 2
LENGTHAFF 0.50 Sample Y Likelihood? B
Incident Description
ORIGIN 5F -- Sewer pumping station Plc
CAUSE 3 -- Overflow
REASON X -- Unknown
NATURE 2A -- Crude Sewage
Comments: BIOLOGY SITE ABOUT 0.75 KM D/S. FOAMING AND DISCOLOURATION.

Catch 29C SITE NR06.2923 URN R29C006 RECNO 26
DATE 02/07/91
RIVER (TRIB) LEW
NAME HALWILL STW
PILS Number 6200291 POLLNGR SX44609960 CATEGORY 2
LENGTHAFF 0.00 Sample Y Likelihood? B
Incident Description
ORIGIN 4A -- SW STW
CAUSE 6 -- Effluent discharge
REASON 6 -- Poor management control
NATURE 2B -- Treated Sewage Effluent
Comments: LENGTH AFFECTED NOT KNOWN. INVERTEBRATE CHANGE NOTED OVER 500M. SITES 4KM D/S.

Catch 29C SITE NR06.2923 URN R29C006 RECNO 29
DATE 07/07/91
RIVER (TRIB) LEW
NAME SWSL
PILS Number 62002918 POLLNGR SX48309950 CATEGORY 2
LENGTHAFF 0.50 Sample Y Likelihood? B
Incident Description
ORIGIN AB -- Treated water distribution
CAUSE 1 -- Leakage
REASON 6 -- Poor management control
NATURE 1X -- Other Chemical
Comments: SUPERCHLORINATED WATER ACCIDENTLY RELEASED. FISH KILL IMMEDIATELY D/S.

Catch 29C SITE NR06.2952 URN R29C009 RECNO 147
DATE 10/12/92
RIVER LEW
NAME WEST DEVON MEAT LTD, HATHERLEIGH
PILS Number 62007918 POLLNGR SS53400480 CATEGORY 2
LENGTHAFF 0.10 Sample Y Likelihood? B
Incident Description
ORIGIN 2B -- Abattoirs
CAUSE 8 -- Direct discharge
REASON 6 -- Poor management control
NATURE 2K -- Animal waste/slurry
Comments: RUNOFF FROM FIELDS TO POND WHICH OVERFLOWED TO LEW. SITES ABOUT 150 M D/S

Catch 29C SITE NR06.2947 URN R29C010 RECNO 53
DATE 21/11/91
RIVER (TRIB) WALDON
NAME WEST DOWN FM, BRADWORTHY, HOLSWOR.
PILS Number 31001464 POLLNGR SS30101450 CATEGORY 1
LENGTHAFF 0.20 Sample Y Likelihood? U
Incident Description
ORIGIN 3A -- Cattle slurry store
CAUSE 3 -- Overflow
REASON 4 -- Poor maintenance
NATURE 2K -- Animal waste/slurry
Comments: SITES 2.5 KM D/S ON WALDON. TRIB ONLY AFFECTED. SEWAGE FUNGUS IN STREAM.

Catch 29C SITE NR06.2957 URN R29C026 RECNO 79
DATE 19/03/92
RIVER (TRIB) NORTHLEW STREAM
NAME HARRATHORN FARM, NORTH LEW
PILS Number 62000758 POLLNGR SX52309760 CATEGORY 2
LENGTHAFF 0.00 Sample Y Likelihood? B
Incident Description
ORIGIN 3A -- Cattle slurry store
CAUSE 3 -- Overflow
REASON 5 -- Poor operational practise
NATURE 2G -- Other sludge
Comments: LENGTH AFFECTED NOT SPECIFIED. SITES 2 KM D/S. DISCHARGE FROM OVERFLOWING LAGOON TO STREAM.

IDENTIFICATION OF POLLUTION INCIDENTS POTENTIALLY AFFECTING
ROUTINE MONITORING SITES 1991 - 1992

Page No. 24
18/06/93

Catch 29C SITE NR06.2945 URN R29C033 RECNO 75
DATE 12/03/92
RIVER (TRIB) TORRIDGE
NAME SUDDON FARM, NEWTON ST PETROCK
PILS Number 62007375 POLLNGR SS41901130 CATEGORY 2
LENGTHAFF 1.00 Sample Y Likelihood? U
Incident Description
ORIGIN 3W -- Farm drainage
CAUSE 9 -- Runoff
REASON 6 -- Poor management control
NATURE 2K -- Animal waste/slurry
Comments: SITES 2.5 KM D/S..

Catch 29C SITE NR06.2949 URN R29C042 RECNO 80
DATE 30/03/92
RIVER WALDON
NAME STRAWBERRY BANKS FM, MILTON DAMEREL
PILS Number 62006756 POLLNGR SS38901070 CATEGORY 2
LENGTHAFF 1.00 Sample Y Likelihood? B
Incident Description
ORIGIN 3W -- Farm drainage
CAUSE 9 -- Runoff
REASON 6 -- Poor management control
NATURE 2K -- Animal waste/slurry
Comments: SITES 1.5 KM D/S.

Catch 29C SITE NR06.2949 URN R29C042 RECNO 122
DATE 03/11/92
RIVER (TRIB) WALDON
NAME HOLSWORTHY BEACON STW
PILS Number 62007911 POLLNGR SS36050815 CATEGORY 2
LENGTHAFF 0.05 Sample Y Likelihood? U
Incident Description
ORIGIN 4A -- SWW STW
CAUSE 6 -- Effluent discharge
REASON C -- Inadequate design/capacity
NATURE 2B -- Treated Sewage Effluent
Comments: SITES 3 KM D/S.

Catch 29C SITE NR06.2959 URN R29C043 RECNO 175
DATE 25/08/92
RIVER COOKBURY STREAM, TRIB WALDON
NAME BICKFORD ARMS, HOLSWORTHY
PILS Number 62006163 POLLNGR SS41100390 CATEGORY 2
LENGTHAFF 0.30 Sample Y Likelihood? U
Incident Description
ORIGIN 4C -- Septic tank
CAUSE 6 -- Effluent discharge
REASON C -- Inadequate design/capacity
NATURE 2B -- Treated Sewage Effluent
Comments: SITES ABOUT 3 KM DOWNSTREAM

Catch 29D SITE NR06.2932 URN R29D002 RECNO 134
DATE 28/10/91
RIVER WEST OKEMENT
NAME MELDON QUARRY
PILS Number 31001295 POLLNGR SX57509400 CATEGORY 1
LENGTHAFF 5.00 Sample Y Likelihood? A
Incident Description
ORIGIN 9W -- Other chemical
CAUSE 9 -- Runoff
REASON 7 -- Weather
NATURE 1X -- Other Chemical
Comments: METEORBURST ALARM AT 1000 AFTER HEAVY RAIN. PH AND METALS. FISH KILL: 32 TROUT AND 62 SALMON FRY.

Catch 29D SITE NR06.2926 URN R29D004 RECNO 33
DATE 20/07/91
RIVER OKEMENT
NAME APPLIEDORE FARM, SAMPFORD COURTNEY
PILS Number 62002421 POLLNGR SX61309770 CATEGORY 1
LENGTHAFF 2.00 Sample Y Likelihood? B
Incident Description
ORIGIN 3P -- Silage stores
CAUSE 6 -- Effluent discharge
REASON 4 -- Poor maintenance
NATURE 2H -- Silage liquor
Comments: SITES 3KM D/S. 500 CUBIC M SILAGE EFFLUENT TO LAND DRAIN. LARGE FISH KILL - OVER 1500.

IDENTIFICATION OF POLLUTION INCIDENTS POTENTIALLY AFFECTING
ROUTINE MONITORING SITES 1991 - 1992

Page No. 25
18/06/93

Catch 29D SITE NR06.2972 URN R29D006 RECNO 7
DATE 10/02/91
RIVER OKEMENT (WEST)
NAME MELDON QUARRY LTD
PILS Number 62001907 POLLNGR SX56809250 CATEGORY 1
LENGTHAFF 17.00 Sample Y Likelihood? A

Incident Description

ORIGIN 92 -- Other Mine/Quarry or Mineral industrial
CAUSE 6 -- Effluent discharge
REASON 5 -- Poor operational practise
NATURE 1C -- Alkali

Comments: 1000 DEAD FISH. DISCOLOURATION, ACIDIC/METALLIFEROUS DISCHARGE OVER WHOLE LENGTH WEST OKEMENT. OTHER SITES AFFECTED: R29D026/2964; R29D003/2925; R29D008/2965; R29D005/2927; R29D006/2966

Catch 29D SITE NR06.2933 URN R29D007 RECNO 16
DATE 09/04/91
RIVER HOLE BROOK
NAME GRT CLISTON FM, EXBOURNE, OKEHAMPT.
PILS Number 62002193 POLLNGR SS61800180 CATEGORY 2
LENGTHAFF 8.00 Sample Likelihood? A

Incident Description

ORIGIN 3A -- Cattle slurry store
CAUSE 4 -- Burst
REASON C -- Inadequate design/capacity
NATURE 2K -- Animal waste/slurry

Comments: SITES 5KM D/S ON HOLE BROOK. OTHER SITES AFFECTED: R29D006/2966 6 KM D/S ON OKEMENT. DISCOLOURATION.

Catch 29D SITE NR06.2933 URN R29D007 RECNO 100
DATE 18/06/92
RIVER HOLE BROOK
NAME GRT CLISTON FM, SAMPFORD COURTNEY
PILS Number 62006329 POLLNGR SS61800190 CATEGORY 1
LENGTHAFF 4.00 Sample Y Likelihood? B

Incident Description

ORIGIN 3A -- Cattle slurry store
CAUSE 1 -- Leakage
REASON 6 -- Poor management control
NATURE 2K -- Animal waste/slurry

Comments: 20,000 GALS SLURRY. 490 DEAD FISH.

Catch 29D SITE NR06.2972 URN R29D030 RECNO 19
DATE 26/04/91
RIVER WEST OKEMENT RIVER
NAME MELDON QUARRY, OKEHAMPTON
PILS Number 62001910 POLLNGR SX56509330 CATEGORY 2
LENGTHAFF 0.00 Sample Y Likelihood? A

Incident Description

ORIGIN 9N -- Other chemical
CAUSE 6 -- Effluent discharge
REASON 5 -- Poor operational practise
NATURE 1C -- Alkali

Comments: DISCHARGES OF LIME. LENGTH AFFECTED NOT KNOWN.

Catch 30A SITE NR06.3037 URN R30A003 RECNO 42
DATE 19/08/91
RIVER VENN
NAME NRA ENGINEERS AT LANDKEY
PILS Number 62002276 POLLNGR SS59903090 CATEGORY 2
LENGTHAFF 1.00 Sample Y Likelihood? A

Incident Description

ORIGIN 1D -- Public highway - Road construction/maintenance
CAUSE B -- Deliberate introduction
REASON A -- SW land drainage work
NATURE 4P -- Surface water

Comments: MAJOR SUSPENDED SOLIDS POLLUTION.

Catch 30A SITE NR06.0710 URN R30A004 RECNO 39
DATE 09/08/91
RIVER VENN
NAME CODDEN FARM, BISHOPS TAWTON
PILS Number 31001369 POLLNGR SS57902990 CATEGORY 2
LENGTHAFF 1.50 Sample Y Likelihood? B

Incident Description

ORIGIN 3A -- Cattle slurry store
CAUSE 3 -- Overflow
REASON 2 -- Accident
NATURE 2K -- Animal waste/slurry

Comments: NO BIOLOGY SITE D/S. 2000 GALLONS SLURRY.

IDENTIFICATION OF POLLUTION INCIDENTS POTENTIALLY AFFECTING
ROUTINE MONITORING SITES 1991 - 1992

Page No. 26
18/06/93

Catch 30B SITE NR06.3043 URN R30B004 RECNO 72
DATE 20/02/92
RIVER (TRIB) TAW
NAME CLEAVE COPSE, UMBERLEIGH
PILS Number 31001495 POLLNGR SS63202150 CATEGORY 1
LENGTHAFF 8.00 Sample Y Likelihood? A
Incident Description
ORIGIN 2G -- Industrial premises - (Organic other)
CAUSE B -- Deliberate introduction
REASON 5 -- Poor operational practise
NATURE 4P -- Surface water
Comments: SITES 3 KM D/S.

Catch 30B SITE NR06.3009 URN R30B007 RECNO 32
DATE 18/07/91
RIVER MULLY BROOK
NAME COLDHARBOUR FM, ASHREIGNEY, CHULML.
PILS Number 62002418 POLLNGR SS60601270 CATEGORY 1
LENGTHAFF 3.00 Sample Y Likelihood? U
Incident Description
ORIGIN 3A -- Cattle slurry store
CAUSE 1 -- Leakage
REASON C -- Inadequate design/capacity
NATURE 2K -- Animal waste/slurry
Comments: SITES 5KM D/S.

Catch 30B SITE NR06.3046 URN R30B008 RECNO 117
DATE 07/10/92
RIVER HOLLOCOMBE WATER
NAME REYNOLDS BOUGHTON LTD
PILS Number 62006924 POLLNGR SS61700950 CATEGORY 1
LENGTHAFF 3.00 Sample Y Likelihood? A
Incident Description
ORIGIN 2Z -- Industrial premises - Other
CAUSE 2 -- Spillage
REASON X -- Unknown
NATURE 1A -- Organic Chemical
Comments: ABOUT 5 GALLONS DETERGENT, WATER WHITE.

Catch 30B SITE NR06.3011 URN R30B012 RECNO 37
DATE 05/08/91
RIVER HAWKRIDGE BROOK VIA DRAIN
NAME ACLAND BARTON, FILLEIGH, BARNSTAPLE
PILS Number 62002430 POLLNGR SS65102730 CATEGORY 1
LENGTHAFF 1.00 Sample Y Likelihood? B
Incident Description
ORIGIN 3A -- Cattle slurry store
CAUSE 1 -- Leakage
REASON 6 -- Poor management control
NATURE 2K -- Animal waste/slurry
Comments: SITES 2KM D/S. SEWAGE FUNGUS.

Catch 30B SITE NR06.3044 URN R30B015 RECNO 141
DATE 25/09/92
RIVER (LITTLE DART) TAW
NAME UNKNOWN
PILS Number 62006176 POLLNGR SS60852370 CATEGORY 2
LENGTHAFF 26.00 Sample N Likelihood? A
Incident Description
ORIGIN 3Z -- Farm premises/land other
CAUSE X -- Unknown
REASON X -- Unknown
NATURE 2K -- Animal waste/slurry
Comments: INCIDENT ABOUT 30 HOURS. NO FISH KILL. FOAM - ALL OF D/S STRETCH OF RIVER AFFECTED. OTHER SITES AFFECTED: R30B014/3006; R30B005/3007.

Catch 30C SITE NR06.3041 URN R30B001 RECNO 40
DATE 13/08/91
RIVER TAW
NAME HAWKRIDGE FM, COLERIDGE, CREDITON
PILS Number 62002434 POLLNGR SS69800870 CATEGORY 1
LENGTHAFF 0.80 Sample Y Likelihood? U
Incident Description
ORIGIN 3N -- Silage effluent tank
CAUSE X -- Unknown
REASON X -- Unknown
NATURE 2H -- Silage liquor
Comments: SITES 2KM D/S. SEWAGE FUNGUS.

IDENTIFICATION OF POLLUTION INCIDENTS POTENTIALLY AFFECTING
ROUTINE MONITORING SITES 1991 - 1992

Page No. 27
18/06/93

Catch 30C SITE NR06.3013 URN R30C002 RECNO 156
DATE 29/01/92
RIVER (TRIB) TAW
NAME GRASSLANDS RESEARCH, ROWDEN FARM
PILS Number 31001485 POLLNGR SX64509920 CATEGORY 1
LENGTHAFF 0.30 Sample Y Likelihood? U
Incident Description
ORIGIN 3W -- Farm drainage
CAUSE 6 -- Effluent discharge
REASON 6 -- Poor management control
NATURE 2K -- Animal waste/slurry
Comments: SITES ABOUT 1 KM D/S.

Catch 30C SITE NR06.3050 URN R30C005 RECNO 96
DATE 30/05/92
RIVER BULLOW BROOK
NAME INCH'S CIDER, WINKLEIGH
PILS Number 62006676 POLLNGR SS62700790 CATEGORY 1
LENGTHAFF 3.00 Sample Y Likelihood? U
Incident Description
ORIGIN 2Z -- Industrial premises - Other
CAUSE 6 -- Effluent discharge
REASON 2 -- Accident
NATURE 2J -- Industrial effluent
Comments: SITES 6 KM D/S. 200 CUBIC METRES TREATED FINAL EFFLUENT.

Catch 30C SITE NR06.3014 URN R30C006 RECNO 104
DATE 06/07/92
RIVER (TRIB) TAW
NAME THE GRANGE, COLDRIDGE, CREDITON
PILS Number 62006690 POLLNGR SS69700770 CATEGORY 1
LENGTHAFF 0.60 Sample Y Likelihood? U
Incident Description
ORIGIN 3F -- Cattle slurry treatment plant
CAUSE 6 -- Effluent discharge
REASON 2 -- Accident
NATURE 2K -- Animal waste/slurry
Comments: SITES 2.5 KM D/S. 6 CUBIC M SLURRY TO VERY LOW TRIB OF TAW.

Catch 30D SITE NR06. URN RECNO 158
DATE 23/03/92
RIVER TRIB LAFORD YEO
NAME WALSON BARTON FARM, BOW
PILS Number 62000859 POLLNGR SS73400080 CATEGORY 2
LENGTHAFF 0.20 Sample Y Likelihood?
Incident Description
ORIGIN 3F -- Cattle slurry treatment plant
CAUSE 3 -- Overflow
REASON 4 -- Poor maintenance
NATURE 2K -- Animal waste/slurry
Comments: NO SITES DOWNSTREAM. FUNGUS.

Catch 30D SITE NR06.3055 URN R30D013 RECNO 99
DATE 16/06/92
RIVER (TRIB) KNIGHTY BROOK
NAME MIDDLE WEEKE FARM, MORGARDBISH100
PILS Number 62006582 POLLNGR SS76200560 CATEGORY 0
LENGTHAFF 0.50 Sample Y Likelihood? U
Incident Description
ORIGIN 3P -- Silage stores
CAUSE 1 -- Leakage
REASON C -- Inadequate design/capacity
NATURE 2H -- Silage liquor
Comments: SITES 2.5 KM D/S.

Catch 30E SITE NR06.3020 URN R30E003 RECNO 47
DATE 04/09/91
RIVER LITTLE DART, TAW
NAME MOORTOWN PIGGERY, CHAWLEIGH
PILS Number 62002440 POLLNGR SS69901330 CATEGORY 1
LENGTHAFF 0.40 Sample Y Likelihood? U
Incident Description
ORIGIN 3K -- Pig slurry treatment plant
CAUSE 6 -- Effluent discharge
REASON 5 -- Poor operational practise
NATURE 2K -- Animal waste/slurry
Comments: SITES 2.5KM D/S. LOCAL FISH KILL.

IDENTIFICATION OF POLLUTION INCIDENTS POTENTIALLY AFFECTING
ROUTINE MONITORING SITES 1991 - 1992

Page No. 28
18/06/93

Catch 30F SITE NR06.3022 URN R30F001 RECNO 30
DATE 17/07/91
RIVER MOLE
NAME GRT HEASLEY FM, SOUTH MOLTON
PILS Number 62002417 POLLNGR SS73003230 CATEGORY 1
LENGTHAFF 1.00 Sample Y Likelihood? U
Incident Description
L ORIGIN 3P -- Silage stores
CAUSE 6 -- Effluent discharge
REASON C -- Inadequate design/capacity
NATURE 2H -- Silage liquor
Comments: UP TO 50 CUBIC M VIA LAND DRAIN TO STREAM. SEWAGE FUNGUS.

Catch 30F SITE NR06.3062 URN R30F023 RECNO 133
DATE 15/07/91
RIVER (TRIB) CROOKED OAK
NAME WEST BULLERFORD FARM, KNOWSTONE
PILS Number 62002413 POLLNGR SS80902540 CATEGORY 1
LENGTHAFF 1.00 Sample Y Likelihood? U
Incident Description
L ORIGIN 3P -- Silage stores
CAUSE 6 -- Effluent discharge
REASON C -- Inadequate design/capacity
NATURE 2H -- Silage liquor
Comments: UP TO 100 CUBIC M. SITES ABOUT 3 KM D/S. AQUATIC LIFE AFFECTED.

Catch 30G SITE NR06.3069 URN R30G013 RECNO 102
DATE 01/07/92
RIVER MADRID WATER
NAME CONTI PRODUCTS, HILL VILLAGE, STH M
PILS Number 62006689 POLLNGR SS68702620 CATEGORY 1
LENGTHAFF 0.00 Sample Y Likelihood? B
Incident Description
L ORIGIN 2D -- Timber processing
CAUSE 6 -- Effluent discharge
REASON C -- Inadequate design/capacity
NATURE 4N -- Process water
Comments: LENGTH AFFECTED NOT SPECIFIED. SITES 2 KM D/S.